

**LIST OF REPORTS SENT TO THE SPONSORER FROM 1st JANUARY, 2016 TO JULY, 2021**

SL.NO.	DATE OF SUBMISSION TO THE SPONSOR	SENDING FINANCIAL YEAR	PROJECT FINANCIAL YEAR	PROJECT NO.	PROJECT TITLE	SPONSOR
1.	08.01.2016	2015-16	2013-14	CNP/3714/2013-14	Study and advice on safety of Patal Bhubaneswar Cave Pithoragarh, Uttarakhand	Archaeological Survey of India, Dehradun
2.	08.02.2016	2015-16	2015-16	CNP/4312/2015-16	Assessment of winding ropes of Narwapahar Mines, UCIL by nondestructive method	Narwapahar Mines, UCIL, Singhbhum (East)
3.	19.02.2016	2015-16	2011-12	CNP/2928/2011-12	Study and failure analysis of 32mm diameter guide rope of K.B. 10/12 pits colliery, BCCL, Dhanbad".	10/12 Pits Colliery, BCCL, Dhanbad
4.	23.03.2016	2015-16	2015-16	CNP/4212/2015-16	In-Situ study and advice on the present condition of four nos of track ropes and two nos. Of haulage ropes of passenger cable car aerial ropeway installation of M/s Timber Trail, Asia Resorts Limited, Parwanoo (H.P.) – Two visits	Asia Resorts Limited, Parwanoo (H.P.)
5.	23.03.2016	2015-16	2014-15	CNP/4121/2014-15	Scientific study and advice for status of goaf atmosphere during extraction of blasting gallery panel No.BG-J(3) in No.3 seam at GDK 11 Incline, Ramagundam Area -I, SCCL	The Singareni Collieries Company Limited, Kothagudam Collieries- 507101, Bhadrachalam Road Railway Station, Dist-Khammam (A.P.)
6.	28.03.2016	2015-16	2015-16	CNP/4345/2015-16	Investigation into drop and spark sensitivity of Nonel tubes and VOD, Sensitivity and density parameters of cast boosters involved in the accidental initiation at Amalgamated Block-II OCP	Block II Area, BCCL, Nawagarh, Dhanbad
7.	05.05.2016	2016-17	2010-11	CNP/2859/2010-11	Studies on failure of 25mm diameter 6X8 FS construction winding rope of victory 2 pit (south side) Bastacolla	Bastacolla Area-IX, BCCL, Dhanbad

					Area,”. BCCL, Dhanbad	
8.	13.05.2016	2016-17	2015-16	CNP/4369/2015-16	“Evaluation and advice on the present condition of haulage rope of fixed grip mono-cable passenger ropeway at Digha, Dist.Purba Medinipur, West Bengal”.	Damodar Ropeways & Infra Limited, Vansittart Row, Kolkata
9.	13.05.2016	2016-17	2016-17	CNP/4381/2016-17	Evaluation and advice on the present condition of haulage rope of mono-cable passenger ropeway at Science City,Kolkata, West Bengal”.	Damodar Ropeways & Infra Limited, Vansittart Row, Kolkata
10.	15.06.2016	2016-17	2011-12	CNP/3064/2011-12	Failure analysis of 32mm diameter guide rope of 6 pit Mine of Katras Choitudih Colliery, Katras Area, BCCL, Dhanbad	Katras Choitudih Colliery, BCCL, Sijua, Dhanbad
11.	29.06.2016	2016-17	2016-17	CNP/4394/2016-17	Advice on suitability of permitted explosive and detonator involved in accident at Chhatarpur Mine No.1, WCL for use in underground coal mines	Pathakhera Area, WCL, Dist-Betul (M.P.)
12.	08.07.2016	2016-17	2016-17	CNP/4383/2016-17	In-Situ non-destructive evaluation and advice on the present condition of track and haulage ropes of bi-cable aerial ropeway passenger cable car installation at Gangtok, Sikkim	Damodar Ropeways & Infra Limited, Vansittart Row, Kolkata
13.	11.07.2016	2016-17	2012-13	CNP/3236/2012-13	Ventilation investigation and advice to improve ventilation at Orient Mine No. 3, MCL	Orient Area, MCL, Brajrajnagar, Dist – Jharsuguda, Odisha - 768216
14.	11.07.2016	2016-17	2015-16	CNP/4356/2015-16	Advice on suitability of coal delay detonators with NHN for use in underground coal mines	PREMIER EXPLOSIVES LTD., /”Premier House” # 11, Ishaq Colony, Secunderabad – 500 015,A.P.

15.	13.07.2016	2016-17	2012-13	CNP/N/3332/2012-13	Geotechnical study for advice on the stability of tailing dam Codli Mine	Sesa Goa Limited (Vedanta), SesaGhor, 20 EDC Complex, Patto, Panjim, Goa – 403001
16.	19.07.2016	2016-17	2016-17	CNP/4382/2016-17	Analysis of Airborne Respirable dust samples from Block-B Project (NCL)	Block-B Project, Gorbi, Dist-Singrauli (M.P.)
17.	06.07.2016	2016-17	2015-16	CNP/4230/2015-16	Subsidence prediction due to extraction of 2S panel of XV seam with hydraulic sand stowing at Jamadoba colliery of Tata Steel limited.	M/s Tata Steel Limited, Jharia Collieries, Jamadoba-828112 Dist: Dhanbad
18.	06.07.2016	2016-17	2016-17	CNP/4401/2016-17	Feasibility of extraction in 6-S panel of IX seam with hydraulic sand stowing at 6 and 7 pits Bhutgoria Amalgamated Colliery of Tata Steel Limited	TATA STEEL LTD
19.	22.07.2016	2016-17	2015-16	CNP/4407/2015-16	Evaluation of Rock Mass Rating (RMR) for Lajkura seam workings at 46 LN panel, Mine No.3, Orient Area, MCL	Orient Area, MCL, Brajrajnagar, Jharsuguda, Odisha - 768216
20.	22.07.2016	2016-17	2015-16	SSP/94/2015-16	In-Situ evaluation and advice on the present condition of winder ropes of main & 3rd stage winders (cage & skip) of Jaduguda Mine (UCIL)	Jaduguda Mines, UCIL, Singhbhum (East)
21.	21.07.2016	2016-17	2015-16	CNP/4375/2015-16	Advice to assess and design the barrier thickness between the running Gopinathpur O/C working and Pusai & Khoodia river nearby with suitable stability aspects.	Sr. Manager Gopinathpur Colliery, Mugma Area Nirsa - 828205, Dist - Dhanbad.
22.	26.07.2016	2016-17	2015-16	SSP/N/98/2015-16	Estimation of RMR and Support Design of stope for Ramrama Underground Managanese Mine	A.P.TRIVEDI SONS
23.	05.08.2016	2016-17	2014-15	CNP/4140/2014-15	Advice on feasible mining methods in coal seams in total perspectives with an aim to have no adverse impact due to mining subsidence on surface at Lohapatti	Western Jharia Area, BCCL, Moonidih, Dhanbad

					Colliery, West Jharia Area, BCCL	
24.	05.08.2016	2016-17	2015-16	CNP/4272/2015-16	Scientific study for designing a suitable method for systematic liquidation of already developed contiguous workings and further development of Lajkura seam at Orient Colliery Mine No. 3, Orient Area, MCL	Orient Area, MCL, Brajrajnagar, Jharsuguda, Odisha - 768216
25.	08.08.2016	2016-17	2016-17	CNP/4411/2016-17	Advice on design of support system for development workings at Sial Ghori Mine, Chhindwara Mine, M.P.	Reliance Cement Co. Pvt. Ltd., Sial Ghori Coal Mine, Gulabra, Chhindwara (M.P.)
26.	08.08.2016	2016-17	2016-17	CNP/4397/2016-17	In-Situ investigation and advice on the present condition of four nos of track ropes and two nos. of haulage ropes of passenger cable car aerial ropeway installation of M/s Timber Trail, Asia Resorts Limited, Parwanoo (H.P.) - Two visits	ASIA RESORTS LTD, PARWANOO (H.P.)
27.	12.08.2016	2016-17	2015-16	CNP/4322/2015-16	Scientific study for design of continuous miner panels in No.2 seam and Salarjung seam of Shantikhani Mandamarri Area, SCCL.	The Singareni Collieries Company Limited, Kothagudam Collieries- 507101, Bhadrachalam Road Railway Station, A.P. Dist-Khammam (A.P.)
28.	17.08.2016	2016-17	2015-16	CNP/4357/2015-16	Advice on suitability of Colex-1 emulsion explosives for use in underground coal mines as a P1 explosives.	PREMIER EXPLOSIVES LTD., "Premier House" # 11, Ishaq Colony, Secunderabad – 500 015, A.P.
29.	16.08.2016	2016-17	2014-15	CNP/3978/2014-15	Periodic evaluation and advice on quality of permitted explosives, detonators, SMS/SME, ID explosives and accessories supplied to SCCL for blasting in underground and opencast	The Singareni Collieries Company Limited, Kothagudam Collieries- 507101, Bhadrachalam Road Railway Station, A.P. Dist-Khammam (A.P.)

					coal mines.	
30.	18.08.2016	2016-17	2016-17	CNP/4412/2016-17	Scientific study to assess the Crossing point temperature and Incubation period of 46LN section of Lajkura seam, Orient Colliery-3, Orient Sub Area, MCL and advice thereof	Orient Area, MCL, Brajrajnagar, Jharsuguda, Odisha - 768216
31.	17.08.2016	2016-17	2015-16	CNP/4364/2015-16	Determination of crossing point temperature, Ignition point temperature and incubation period of Lignite seam, Barsingsar Mine, NCL, Rajasthan and advice thereof.	Neyveli Lignite Corporation Limited, Barsingsar Lignite Mine, Udairamsar, Barsingsar – 334 402, Rajasthan
32.	22.08.2016	2016-17	2015-16	CNP/4318/2015-16	Advice on design of suitable support system for Chanda Rayatwari Colliery, UG Mine, Chandrapur Area	Dy. General Manager(M)/Sub Area Manager, Rayatwari Sub Area, WCL, P.O.- Babupeth, Dist- Chandrapur (Rajasthan)
33.	22.08.2016	2016-17	2014-15	CNP/4145/2014-15	Control of open fire at 23 D near B-shaft in R-VI seam at MIC unit of Jhanjra Project colliery, ECL.	Jhanjra Area, ECL, P.O.- Jhanjra (B.O.), Dist-Burdwan
34.	30.08.2016	2016-17	2013-14	CNP/3838/2013-14	Periodic evaluation and advice on quality of SMS / SME of SCCL owned plants and OC/UG explosives and accessories of other firms	The Singareni Collieries Company Limited, Kothagudam Collieries- 507101, Bhadrachalam Road Railway Station, Dist-Khammam (A.P.)
35.	30.08.2016	2016-17	2015-16	SSP/86/2015-16	Investigation on methane emission at R-IV and R-VI Coal seams of Pandaveswar colliery for the categorization of degree of gassiness and advice on associated gas hazards.	Pandaveswar Area, ECL, Burdwan (W.B.)
36.	30.08.2016	2016-17	2016-17	CNP/4408/2016-17	Advice on the use of coal ash from Korba Thermal Super Thjermal Power Station, NTPC for underground stowing at SECL Mines	Korba Thermal Super Thjermal Power Station, NTPC, Jamnipalli, Korba, C.G.

37.	02.09.2016	2016-17	2016-17	CNP/4399/2016-17	Evaluation of Rock Mass Rating (RMR) for VII top seam workings at 6 pit, Bararee Colliery, Lodna Area, BCCL	Bararee Colliery, BCCL, BhulanBararee -838133, Dhanbad
38.	12.09.2016	2016-17	2016-17	SSP/136/2016-17	Assessment and advice on surface temperature rise of HT Induction Flameproof motor rated at 750KW, 4 Pole, 6.6KV in frame size:KF450, suitable for use in hazardous area	M/s Marathon Electric Motors (India) Ltd., Large Machine Unit, 1, Taratala Road, Kolkata -700 024
39.	01.09.2016	2016-17	2015-16	SSP/103/2015-16 & CNP/4352/2015-16	Safety evaluation of different surface features and structures lying over depillaring panels in Jharia Coalfield of Tata Steel.	TATA STEEL LTD
40.	01.09.2016	2016-17	2015-16	CNP/4231/2015-16	Subsidence prediction due to extraction of 2S panel of XI seam with hydraulic sand stowing at Jamadoba colliery of TaTa Steel Limited.	TATA STEEL LTD
41.	16.09.2016	2016-17	2015-16	CNP/4253/2015-16	Study of impact of Fly ash filling on flora, fauna, aquatic lives and habitat, water and air quality prior and during the course of ash dumping in mine.	CESC LTD
42.	22.09.2016	2016-17	2015-16	CNP/4303/2015-16	Advice on design of support for installation of Pulley Station of Man Riding Chair Lift System for transportation in Jijua Colliery, Jharia Division, Tata Steel Limited	Tata Steel Limited
43.	27.09.2016	2016-17	2015-16	CNP/4372/2015-16	Determination of Crossing point temperature, Ignition point temperature of seam VII and seam VI(B) of Khairaha underground Mine, Sohagpur Area, SECL and advice thereof	Rajendra UG Mine, Rajendra SubArea, Sohagpur Area, SECL, Shahdol M.P.
44.	27.09.2016	2016-17	2016-17	CNP/4430/2016-17	Evaluation and advice on the present condition of haulage rope of Naina Deviji mono-cable aerial ropeway at Shri Naina Deviji, H.P.	Damodar Ropeways & Infra Limited, Kolkata

45.	28.09.2016	2016-17	2015-16	CNP/4216/2015-16	Assessment of electrical safety parameters and advice on partially pressurized type 'Z' purged one no. Ex 'p' local control panel for WET Gas Compressor, CPCL, Chennai in Size 2400(W)X2450(H)X1500(D) for use in Gas Group: IIA & IIB and zone 2 area	Electronics Corporation of India Ltd., Hyderabad
46.	27.09.2016	2016-17	2015-16	CNP/4351/2015-16	Advice on suitability of small diameter emulsion explosive for use in underground coal mines as a P5 explosive	Black Diamond Explosives (P) Limited, Dhanbad
47.	27.09.2016	2016-17	2016-17	SSP/131/2016-17	Assessment of surface temperature rise of FLP/WP bucket mono block pumps, Model:GNB550 FLP in frame size:132 and Model:GNB-370 FLP in frame size:90F suitable for use in gas group I hazardous area	M/s. Harison Pumps Pvt. Ltd., Nagpur
48.	18.09.2016	2016-17	2016-17	CNP/4427/2016-17 & SSP/148/2016-17	Evaluation of emulsion permitted Explosive Supercoal-5 with code no.SEL/EM/03/P5-3 and advice on its suitability for use in underground coal mines	Solar Industries India Limited, Nagpur
49.	19.09.2016	2016-17	2013-14	CNP/3609/2013-14	Feasibility study for installation of sewage treatment plant for colonies of Tata Group of Collieries	Tata Steel Limited, Dhanbad
50.	30.09.2016	2016-17	2015-16	SSP/95/2015-16	Investigation into the drop and spark sensitivity of Nonel tubes involved in the accidental initiation at Amalgamated Block-II OCP	Block II Area, BCCL, P.O.- Nawagarh, Dist-Dhanbad
51.	30.09.2016	2016-17	2015-16	SSP/102/2015-16	Evaluation of small diameter emulsion explosive for assessing its suitability for use in underground coal mines as a P5 explosive	Black Diamond Explosives (P) Limited, Dhansar, Dhanbad

52.	30.09.2016	2016-17	2015-16	SSP/107/2015-16	Evaluation of colex-1 emulsion explosive for assessing its suitability for use in underground coal mines as a P1 Explosive	PREMIER EXPLOSIVES LTD., /"Premier House" # 11, Ishaq Colony, Secunderabad – 500 015,A.P.
53.	03.10.2016	2016-17	2014-15	CNP/4134/2014-15	Periodic evaluation and advice on quality of OC Explosives and accessories supplied by various firms to SCCL	The Singareni Collieries Company Limited, Kothagudam Collieries- 507101, Bhadrachalam Road Railway Station, Dist-Khammam (A.P.)
54.	17.10.2016	2016-17	2016-17	CNP/4410/2016-17	Advice on design of support for inclines at Sial Ghori Mine, Chhindwara, M.P.	Reliance Cement Co.Pvt.Ltd.,SialGhori Coal Mine,House No.82, Asha Bhawan,Ward No.23, Old Labour Court Compound, Gulabra, Chhindwara (M.P.) – 480 001
55.	21.10.2016	2016-17	2013-14	CNP/N/3811/2013-14	Peer Review of underground stoping benchmarking study carried out by Beck Engineering Pty. For Rampur Agucha Mine, HZL	Rampur Agucha Mines, HZL,Agucha – 311 029,Bhilwara,Rajasthan
56.	01.11.2016	2016-17	2016-17	CNP/4425/2016-17 & SSP/146/2016-17	Evaluation of Copper coated steel permitted delay detonators APSPDD (0- 6) and advice on their suitability for use in underground coal mines	M/s A.P. Explosives Pvt.Limited,Plot No.7, H.No.3-47-7, Sripuri Colony, Karkhana, Secunderabad – 500 015(Telangana State)
57.	01.11.2016	2016-17	2015-16	SSP/55/2015-16	Scientific study for monitoring the subsidence of different Strata lying below Dhanbad - Chandrapura railway Line over X Seam fire affected area at Gopal Gareria section of Sendra Bansjora Colliery, BCCL (August'2015 to July'2016)	The Project Officer,Sendra Bansjora Colliery,Sijua Area, BCCL, P.O.-Bansjora,Dist –Dhanbad
58.	04.11.2016	2016-17	2016-17	CNP/4434/2016-17	Study and advice for developing blasting parameters at Bera open cast mine of BCCL for controlling blast induced vibration, flyrocks at houses/structures	Project Officer, Bera Colliery, BCCL, Bastacolla Area No.IX, Dhansar, Dist-Dhanbad



					in the vicinity of inhabitant's area lying in danger zone with improved fragmentation	
59.	04.11.2016	2016-17	2016-17	CNP/4432/2016-17	Performance evaluation of closed circuit compressed oxygen cylinder type breathing apparatus, Model P30 of JSC Donetsk Mines Rescue Equipment Co., Ukrain	Industrial Appliances and Technologies, Madhurima House, Kolkaka-700053
60.	09.11.2016	2016-17	2016-17	SSP/53/2015-16	Assessment and advice on "Monitoring of strata behaviour during extraction of developed pillars in CMP -8 panel at VK 7 Incline , SCCL	The Singareni Collieries Company Limited, Kothagudam Collieries- 507101, Bhadrachalam Road Railway Station, Dist-Khammam (A.P.)
61.	09.11.2016	2016-17	2015-16	CNP/4323/2015-16	Advice on design of support system in gate roadways at Moonidih XV seam longwall panels using bolter miner, M/s Indu Project	Indu SCCL CGM Consortium, Indu Projects, Moonidih – 828 129, Dist-Dhanbad
62.	09.11.2016	2016-17	2016-17	SSP/126/2016-17	Investigation into safety, performance and efficiency of permitted explosive and detonators involved in accident at Chhatarpur Mine No. 1, WCL	Area Safety Officer, Office of the General Manager, Pathakhera Area, WCL, P.O.- Pathakhera, Dist-Betul, Dist-Betul (M.P.)
63.	11.11.2016	2016-17	2015-16	CNP/4288/2015-16	Scientific study on Ventilation system and reorganisation of ventilation system of Kenda seam of Bansara Colliery, Kunustoria Area, ECL	Agent, Bansra Colliery, Kunustoria Area, ECL, P.O.- Bansra Dist-Burdwan (W.B.)
64.	18.11.2016	2016-17	2015-16	SSP/106/2015-16	Evaluation of coal delay detonator with NHN for assessing its suitability for use in underground coal mines	PREMIER EXPLOSIVES LTD., "Premier House" # 11, Ishaq Colony, Secunderabad – 500 015, A.P.
65.	18.11.2016	2016-17	2016-17	CNP/N/4388/2016-17	Design of stoping geometry and the crown pillar thickness at Kayad Mines, HZL	Rampur Agucha Mine, HZL,

66.	29.11.2016	2016-17	2016-17	CNP/4417/2016-17	Study and advice on Airborne Respirable dust environment of Vijay West Mine, Chirimiri Area, SECL	Sub Area Manager, Rani Atari Sub Area, Chirimiri Area, P.O. – West Chirimiri, Dist – Korea (C.G.)
67.	14.12.2016	2016-17	2016-17	CNP/4416/2016-17	Assessment and technical advice on one no. Flameproof A/C of 5 ton capacity Cat No.SAC/211 for use in Gas Group IIC atmosphere only	M/s Sudhir Switchgears Pvt. Ltd., 305/6, Apeejay House, 130 B.S.Marg, Fort, Mumbai – 400 023
68.	14.12.2016	2016-17	2016-17	CNP/4424/2016-17	Advice on load bearing capacity in order to decide suitability of introduction of Continuous miner of single-pass height of 5.5m in R-VI seam of Khottadih Colliery, ECL: the first time such application in India	Dy. General Manager/Agent, Khottadih Colliery, Office of the Agent, Khottadih Colliery, P.O.- Khottadih, Dist-Burdwan (W.B.) PIN - 713378
69.	16.12.2016	2016-17	2016-17	CNP/4452/2016-17	In-situ investigation and advice on the present condition of haulage rope of D.R.V. passenger Ropeway at Darjeeling, West Bengal – Two visits	DGM (Marketing), Conveyor & Ropeway Services Pvt. Ltd., 75-C, Park Street, 6 <sup>th</sup> Floor, Kolkata -700016
70.	19.12.2016	2016-17	2016-17	CNP/4418/2016-17	Scientific study to liquidate (Development & Depillaring) the Salarjung seam in identified patches (Area 1 & 1A) at Shantikhani Mine with Continuous Mine Technology, Mandamari Area, SCCL	The Singareni Collieries Company Limited, Kothagudam Collieries- 507101, Bhadrachalam Road Railway Station, Dist-Khammam (A.P.)
71.	26.12.2016	2016-17	2016-17	CNP/4380/2016-17	In-situ non-destructive evaluation and advice on the present condition of track and haulage ropes at Nainital Ropeway, Uttarakhand	Operational Manager, Kumaon Mandal Vikas Nigam Ltd., Ropeway Nainital, Ook Park House, Mallital, Nainital-263001 Uttarakhand
72.	26.12.2016	2016-17	2014-15	SSP/31/2014-15	Ground monitoring by instrumentation and advice on stoping parameters of Mahagiri Mines (Chromite) of IMFA Limited	Indian Metals & Ferro Alloys Ltd., IMFA Building, Rasulgarh, Bhubaneswar – 751010, Odisha
73.	29.12.2016	2016-17	2015-16	SSP/N/99/2015-16	Scientific blasting study to recommend safe and productive blasting practice at Madukkarai limestone mine of M/s ACC Limited	Chief Manager (Mines), Madukkarai Cement Works, ACC Limited, P.O.- Madukkarai, Dist – Coimbatore (Tamil Nadu)

74.	27.12.2016	2016-17	2015-16	CNP/4331/2015-16	Study and advice for safe and efficient blasting operations to be conducted at Jayant project beyond 300m from the structures to control vibration within safe limit for the safety of residential houses/ structures in the nearby villages/township of Singrauli	The General ManagerM/s NCL Po- Jayant Dist: Singrauli (MP)
75.	16.01.2017	2017-18	2016-17	SSP/142/2016-17	Slope stability study of Malanjkhanda Copper Project, HCL	DGM (Mines), Malanjkhanda Copper Project DGM (Mines), HCL , Balaghat, M.P.
76.	06.02.2017	2016-17	2016-17	SSP/141/2016-17	Investigation on methane emission and advice on associated gas hazards for classification of degree of gassiness of seam iC, Sial Ghogri coal mine of Reliance Cement Co.Pvt. Ltd., Chhindwara, Madhya Pradesh	RELIANCE CEMENT CO.PVT.LTD., CHHINDWARA, M.P.
77.	07.02.2017	2016-17	2015-16	SSP/58/2015-16	Performance evaluation of LMD having Dynament Limited UK make IR Detector and advice on the Compatibility of the Detector with the LMD (Drager).	M/s Joseph Leslie Dynamiks Mfg.Pvt.Ltd.,Leslico House, Prof.V.S.Agashe Road, Dadar West,Mumbai-400 028
78.	07.02.2017	2016-17	2016-17	CNP/4480/2016-17 & SSP/169/2016-17	Evaluation of Copper coated steel permitted delay detonators APSPDD (0- 6) and advice on their suitability for use in underground coal mines	Managing Director, M/s A.P. Explosives Pvt.Limited, A-14, Vikrampur, Secunderabad – 500009 (Telangana State)
79.	07.02.2017	2016-17	2016-17	SSP/155/2016-17	Assessment and technical advice on surface temperature rise classification and hydraulic of frame proof motor rated at 300KW, 12 Pole, 6.6 KV in Frame size: E560LX for use in hazardous area as per relevant Indian standard	Executive-Design,,Crompton Greaves Limited, Large & Traction Machines Division:Industrial Systems,D5, Industrial Area MPKVN,Mandideep- 462046,Bhopal (M.P.)
80.	07.02.2017	2016-17	2016-17	CNP/4457/2016-17	In-situ Nondestructive evaluation of winding ropes of cage and skip winder running at Narwapahar Mines of UCIL-04 (Four) visits in 02 (Two) years	Addl.Suptd (Mech), Narwapahar Mines,UCIL, Singhbhum (East)Jharkhand- 832111

81.	08.02.2017	2016-17	2013-14	CNP/3853/2013-14	Evaluation of roof rock behavior for depillaring T 9 panel at Tandsi 3&4 Incline , Kanhan Area, WCL	General Manager, Kanhan Area,WCL,P.O. – Dungaria, Dist –Chhindwara (M.P.) PIN - 480553
82.	09.02.2017	2016-17	2014-15	CNP/4202/2014-15	Scientific study and advice for gas investigation in Longwall panel No.1 of No.1 seam at Adriyala Longwall project (ALP) section of GDK No. 10 Incline, SCCL	General Manager(R&D),The Singareni Collieries Company Limited, Kothagudam Collieries-507101Bhadrachalam Road Railway Station,Dist-Khammam(Telangana State)
83.	09.02.2017	2016-17	2014-15	CNP/4020/2014-15	Scientific study and advice for monitoring of environmental conditions in Longwall panel No.1 seam 2 at GDK 10A incline, SCCL	General Manager(R&D),The Singareni Collieries Company Limited, Kothagudam Collieries-507101Bhadrachalam Road Railway Station,Dist-Khammam(Telangana State)
84.	09.02.2017	2016-17	2016-17	CNP/4477/2016-17	Assessment of electrical safety parameters and advice on pressurized (Ex 'P') DC Motor rated at 746KW, 4 Pole, 750V in Frame size OM4903CX as per IS/IEC:60079-2:2007 for use in zone – 1 & 2, Gas Group IIA/IIB hazardous areas as per relevant Indian Standard.	Design Engineer,TME Division,Bharat Heavy Electricals Limited,Block-IX, EW, 1stFloor,Bhopal (M.P.) PIN- 462022
85.	23.03.2017	2016-17	2013-14	CNP/3623/2013-14	Determination of extent of fire near Dhanbad Chandrapura Railway line at Block-II OCP and advice to control of fire.	The General Manager,Block II Area, BCCL,P.O. –Nawagarh, Dist –Dhanbad, PIN - 828 306
86.	29.03.2017	2016-17	2014-15	CNP/4160/2014-15	Advice on method of workings and sequence of extrction of existing coal reserves at Hirakhand Bundia Mine, MCL	General Manager (CP&P), Mahanadi Coalfields Limited,Jagriti Vihar,Burla,Sambalpur,Odisha-768020

87.	30.03.2017	2016-17	2015-16	CNP/4266/2015-16	Study on soundness of mechanical integrity of vital safety components used in Narwapahar Mines. through non-destructive evaluation”	Addl.Suptd (Mech),Narwapahar Mines,UCIL,, Singhbhum (East),Jharkhand-832111
88.	30.03.2017	2016-17	2016-17	CNP/4397/2016-17	In-Situ investigation and advice on the present condition of four nos of track ropes and two nos. of haulage ropes of passenger cable car aerial ropeway installation of M/s Timber Trail, Asia Resorts Limited, Parwanoo (H.P.) – Two visits	Ropeway Incharge,Timber Trail,Asia Resorts Limited,Parwanoo-173220(Himachal Pradesh)
89.	30.03.2017	2016-17	2016-17	CNP/4420/2016-17	Advice for development of Khairaha Mine Block, Sohagpur Area, SECL for introduction of continuous miner	General Manager,JMS Mining Services Private Limited,ASYST Park,2 <sup>nd</sup> Floor,GN-37/1,Salt Lake, Sector-V,Kolkata-700091
90.	31.03.2017	2016-17	2015-16	CNP/4234/2015-16 & SSP/52/2015-16	Study and monitoring of blast-induced ground vibration due to excavation of an additional Adit to Head Race Tunnel (HRT) at Sawra-Kuddu HEP, HPPCL & Advice on safe blast design for excavation of an additional Adit to HRT at Sawra-Kuddu HEP, HPPCL ”.	General Manager,Himachal Pradesh Power Corporation Limited,Sawra Kuddu HEP(111MW), HPPCL, Hatkoti,Tehsil-Jubbai,Dist-Shimla(Himachal Pradesh)PIN -171206
91.	18.04.2017	2017-18	2016-17	CNP/4517/2016-17	Advice on slope stability of pits and external dumps of Ghorhaburhani – Sagasahi Iron Ore Block of Essar India Limited	Sr.Vice President-Mining,Essar Steel India Limited,Bhadrasahi , Ore Club,Barbil,Beside Bank of India,Near Bhadrasahi Chowk,Keonjhar-758 035 (Odisha)
92.	18.04.2017	2017-18	2016-17	CNP/4428/2016-17 & SSP/149/2016-17	Advice in the development of P5 emulsion explosive and advice on its suitability for use in underground coal mines”.	Sr.General Manager(Works),Solar Industries India Limited, 11, ZadeLayout, Bharat Nagar,Nagpur – 440 033

93.	25.04.2017	2017-18	2016-17	SSP/N/129/2016-17	Recommendations on scientific study for deep hole blasting using site mixed emulsion (SME) at Maldi Mopar Limestone Mine	Sr.Manager(Mines),Maldi Mopar Limestone Mine, Ambuja Cements Limited, Unit-Bhatapara P.O. – Rawan, Teh.Baloda Bazar,Bhatapara, Raipur (C.G.) –493 331
94.	02.05.2017	2017-18	2016-17	CNP/4511/2016-17	Advice on slope stability of the coal and OB benches in the hanging wall of an upthrow strike fault in the dip side of the property of New Majri OC-I (A) & II (A) Extn. OCM and Telwasa OCM of Majri Area.	The AGM, M/s WCL, New Majrisub-Area, PO :Shivajinagar, Dist:Chandrapur-PIN: 442503
95.	04.05.2017	2017-18	2015-16	CNP/4302/2015-16	Scientific investigation to assess the status of fire inside the sealed off Mine No.3 of Orient Area, MCL and advice for control measures	M/s. Mahanadi Coalfields Ltd., General Manager, Orient Area, MCL, P.O.-Brajrajnagar - 768216 ,Dist. - Jharsuguda
96.	15.05.2017	2017-18	2016-17	SSP/119/2016-17	Environmental compliances, monitoring and related advice for Kathautia Open Cast Coal Mine.	M/s Hindalco Industries Ltd. M/s Hindalco Industries Ltd. 327/B, Gate No. 4, Ashok Nagar Ranchi-834002, Jharkhand
97.	25.05.2017	2017-18	2016-17	CNP/4492/2016-17	Study and advice for optimization of blast design parameters at Injepalli Limestone Mine of M/s Kesoram Industries Ltd. (Unit-Vasavdatta Cement) to control ground vibration, noise and flyrocks within safe limits for the safety of houses.structures in the periphery of the mine	Kesoram Industries Limited - Cement Division, Unit-Vasavadatta Cement, P.O.- Sedam, Dist-Kalaburagi (Karnataka)
98.	25.05.2017	2017-18	2015-16	CNP/4280/2015-16	Advice for optimization of blast design parameters at Moher and Moher Amlori Extension Open Cast Project for safe and efficient blasting operations	M/s. Sasan Power Limited D. Block, Ground Floor, Dhirubhai Ambani Knowledge City Koparkhairane, Navi Mumbai - 400710, Maharashtra, India

99.	08.06.2017	2017-18	2015-16	CNP/4373/2015-16	Advice on casing characteristics and ground movement behaviour in 124LW panel with continuous miner deployment at churcha, RO, SECL	Sub Area Manager, Churcha RO Baikunthpur Area, Distt - Korea (CG) -497339
100.	08.06.2017	2017-18	2015-16	SSP/41/2015-16	Scientific study for strata behaviour evaluation and strata management in 124LE panel of East Block of Churcha (RO) mine with continuous miner deployment	General Manager(M), Churcha Mine (R.O.), Baikunthpur Area, SECL, Dist-Korea (C.G.) PIN- 497339
101.	08.06.2017	2017-18	2015-16	SSP/111/2015-16	Monitoring of strata behaviour including caving characteristic, convergence, load on support in 124LW CM panel of East Block of Churcha Mine (RO) of SECL	Sub Area Manager, Churcha Mine(R.O.), Baikunthpur Area, SECL, Dist-Korea (C.G.) PIN-497339
102.	08.06.2017	2017-18	2017-18	SSP/188/2017-18	In-situ evaluation and advice on the present condition of winding ropes of main & 3rd stage winders (Cage & Skip) of Jaduguda Mine (UCIL)	Supdt . (Mech), M/s Uranium Corporation of India Ltd., Jaduguda Mines Jharkhand-832102, India
103.	22.06.2017	2017-18	2016-17	CNP/4398/2016-17	Advice on 'Scientific studies for Auditing of Ground control and Management Plan of Kayad Mine of HZL	Unit Head, Kayad Mine, Hindustan Zinc Limited, Ajmer -305 023(Rajasthan)
104.	28.06.2017	2017-18	2015-16	CNP/4263/2015-16	Advice on slope stability at Jhamarkotra Rock Phosphate Mine FOR THE YEAR 2015-2016, Udaipur, Rajasthan, RSMML	Jhamarkotra Mines, The GM (Mining)/Agent, P.O.- Jhamarkotra -313015 Dist.- Udaipur, Rajasthan
105.	03.07.2017	2017-18	2017-18	CNP/4538/2017-18	Advice on use of coal ash from DCP with overburden at Gare Pelam IV/1 opencast mine, Tamner- Phase VI.	The DGM (Environment), JSPL, Raigarh-496001, CG
106.	04.07.2017	2017-18	2015-16	CNP/4304/2015-16 & SSP/73/2015-16	Advice on slope stability condition of Rampura Agucha Mine and Dump, HZL	M/s. Hindustan Zinc Limited, Accounts Officer, Head Office Extension CRDL, Shared Services Center, Zinc Smelter, P.O. Debari, Udaipur - 313024

107.	04.07.2017	2017-18	2016-17	SSP/174/2016-17	Performance evaluation of self contained self rescuer Model OXY 3000 MKII of Drager (Part I)	M/s Drager Safety India Privatelimited, Gurgaon, Mumbai
108.	04.07.2017	2017-18	2016-17	SSP/174/2016-17	Performance evaluation of self contained self rescuer Model OXY 6000 MKII of Drager (Part II)	M/s Drager Safety India Privatelimited, Gurgaon, Mumbai
109.	07.07.2017	2017-18	2016-17	CNP/4395/2016-17 & SSP/127/16-17	(1) Advice on scientific studies for ground control and Management Plan- 2016 for underground working stability at Rampur Agucha Mines of M/s Hindustan Zinc Limited, Rajasthan".(2) "Geotechnical monitoring og u/g workings stability of Rampur Agucha Mine of M/s Hindustan Zinc Limited, Rajasthan, India".	Mine Manager, Rampur Agucha Mines, HZL, Near Gulabpura, P.O.- अगुचा/Agucha – 311 029 Dist-Bhilwara (Rajasthan)
110.	17.07.2017	2017-18	2017-18	CNP/4549/2017-18	Advice for extraction of 6S panel of IX seam with hydraulic sand stowing for safety of surface structures at Digwadih colliery of Tata Steel Limited.	M/s Tata Steel Limited,Digwadih Colliery,Jamadoba Group, JhariaDivision, Dist. Dhanbad,Jharkhand.
111.	17.07.2017	2017-18	2017-18	CNP/4558/2017-18	Technical Inspection and Evaluation of Cross Over-D at Slab Route Near Plant of Dalmia Cement East Limited, Balidih, Bokaro, Dalmia Cement East Ltd.	Dalmia Cement East Ltd.,Plot No.IV/A-7(P) Near IOCL BottlingPlant P.O.-Balidih Dist-Bokaro, Jharkhand -827014
112.	18.07.2017	2017-18	2015-16	CNP/4314/2015-16 & SSP/81/2015-16	Advice on slope stability condition of the active mine and dump slopes of D-Quarry for OMC Ltd., Orisha.	The Regional Manager, M/s OMC, PO. F.C.Plant, Jajpur, Orissa
113.	18.07.2017	2017-18	2016-17	CNP/4471/2016-17	Analysis of Airborne Dust collected on Filter Paper at Baikunthpur Area, SECL	Area Safety Manager,BaikunthpurArea, SECL, Korea, (C.G.)
114.	18.07.2017	2017-18	2014-15	CNP/4193-4194/2014-15 & SSP/39/2014-15	Carrying Capacity study of Saranda Region in West Singhbhum, Jharkhand-Assessment of Impact of Mining and to determine annual production limit of Iron Mine	Dr.Sudhir Kumar,Assistant General Manager,Environment Management Division,Indian Council of Forestry Research and Education(ICFRE),P.O.- New Forest Dehradun-248006



						(Uttarakhand)
115.	19.07.2017	2017-18	2016-17	CNP/4451/2016-17	In-situ evaluation and advice on the present condition of 11 man riding chair car systems and 34 man riding chair lift systems, SCCL	General Manager (R & D)M/s The SCCL Kothagudem Collieries-507101, Dist: Khammam, Telangana
116.	24.07.2017	2017-18	2017-18	SSP/222/2017-18	Generation of Physico-mechanical properties as suggested by Triveni Sainik Mining Private Ltd., of BH# PDH-08 and PDH-12 of Pakari Barwadih West pit, Hazaribag (Jharkhand)	M/s. Triveni Sainik Mining Pvt. Ltd. M/s. Triveni Sainik Mining Pvt. Ltd. Hazaribag (Jharkhand)
117.	01.08.2017	2017-18	2017-18	CNP/4565/2017-18 & SSP/208/2017-18	Analysis and Advice on Geo-technical Data for underground mine design of dip side of Manoharpur Coal Block, Odisha Coal & Power Limited (OCPL).	Dy.General Manager(Commercial & Contracts),Odisha Coal & Power Limited,Zone-A, Ground Floor, Fortune Towers,Chandrasekharpur, Bhubaneswar-751023
118.	01.08.2017	2017-18	2017-18	CNP/4536/2017-18	Advice on slope stability of one external dump (Guruda overburden dump) atTiringpahar manganese mine, Tata Steel Limited	The Head, Manganese Group of Mines, Tata Steel Limited
119.	03.08.2017	2017-18	2015-16	CNP/4313/2015-16	Advice on slope stability condition of the AC-DE Quarry active mine slope, South Kaliapani, OMC, Orissa.	The Regional Manager,M/s OMC, PO. F.C.Plant, Jaipur Orissa.
120.	01.08.2017	2017-18	2015-16	CNP/4363/2015-16	Advice for optimization of blast design parameters at proposed opencast patch at Dalurband Colliery to control vibrations within safe limit in the underground workings of R-VI seam working seam of Khottadih u/g colliery and consequent recommendation of safe ground vibration limit..	The General Manager,M/s ECL,Pandaveswar Area, PO-Pandaveswar,Dist: Burdwan (West Bengal) -713346

121.	03.08.2017	2017-18	2016-17	SSP/150/2016-17	Scientific study for strata monitoring and management plan for extraction of developed pillars by the Continuous Miner in the proposed CM Sub panels- 14, 15 & 16 in R-VII Seam of Sarpi project, SSPur Colliery, Bankola Area, ECL.	The General Manager M/s ECL Bankola Area, Area-VI, PO: Ukhra, Distt: Burdwan-713363
122.	04.08.2017	2017-18	2016-17	CNP/N/4512/2016-17	Design of controlled blasting pattern and practice by using SMS/SME at Penganga Open cast coal mine.	Project Officer, Penganga OC Project, Wani Area, WCLP.O. - Virur- Gadegaon The. Korpana, Chandrapur – 442 917
123.	04.08.2017	2017-18	2017-18	CNP/4594/2017-18	Assessment and advice on the present condition of haulage rope at Nicco Parks & Resorts Limited at Salt Lake, Kolkata, West Bengal	Manager (Engg.Dept.), Nicco Parks & Resorts Limited, Jheel Meel, Sec -IV, Salt Lake City, Kolkata – 700 106
124.	04.08.2017	2017-18	2016-17	CNP/N/4513/2016-17	Design of controlled blasting pattern and practice by using SMS/SME at Mungoli Open cast coal mine	Area General Manager, Wani Area, WCL, Urjagram, Tadali, Tah & Dist- Chandrapur – 442 406 (Maharashtra)
125.	04.08.2017	2017-18	2017-18	SSP/193/2017-18	Insitu evaluation and advice on the present condition of haulage rope of detachable Grip Mono-Cable passenger ropeway at Maihar, M.P.	Damodar Ropeways & Infra Limited, 1/A, Vansittart Row, Kolkata-700001
126.	18.08.2017	2017-18	2017-18	CNP/4554/2017-18	Conducting Laboratory tests of overburden of Gondagaon OCM, Nagpur Area, WCL	GM (Min) WCL, Coal Estate, CIVIL Lines, Nagpur – 440001.
127.	22.08.2017	2017-18	2010-11	CLP/49/2010-11	Development of fire fighting chemicals for control and extinguishment of fires in surface coal mines/coal stacks/overburden dumps and other similar fires	M/s K.V.Fire Chemicals (I) Pvt.Ltd., Kamala Niwas, Plot No.32, Lane-D, Sector-8, Vashi, Navi Mumbai - 400703 (Maharashtra)

128.	24.08.2017	2017-18	2016-17	CNP/4497/2016-17	Scientific investigations for capacity enhancement of 6.7 KM long SEI Dam Tunnel of water resources Department, Zone Jodhpur, Government of Rajasthan, Jodhpur	Executive Engineer, Jawai Canal, Sumerpur Division, Department of Irrigation, Govt. of Rajasthan, Sumerpur-306902
129.	08.09.2017	2017-18	2014-15	CLP/55/2014-15	Development and Evaluation of emulsion permitted (P1, P3 & P5) Explosives suitable for use in Indian underground coal mines".	Chief Operating Officer, IDL Explosives Limited, Kukatpally, Post Bag No.1, P.O. – Sanathnagar (IE)-500 018 (Telengana State)
130.	08.09.2017	2017-18	2017-18	CNP/4542/2017-18	Assessment and advice on the present condition of haulage rope of Mono-Cable passenger ropeway at Science City, Kolkata	The DGM (Operation), Damodar Ropeways & Infra Limited, 1/A, Vansittart Row, Kolkata-700001
131.	08.09.2017	2017-18	2017-18	CNP/4601/2017-18	Evaluation and advice on the present condition of winder ropes of Turamdih Mines of Uranium Corporation of India Limited at Turamdih, Jharkhand".	The Chief Supdt.(Mech), Turamdih Mines, UCIL, P.O. – Sundarnagar, Dist - Singhbhum (East) Jharkhand-832107
132.	13.09.2017	2017-18	2016-17	CNP/4523/2016-17	Advice on support Design for 5.5 M width roadways with bolter miner at Adriyala Longwall Project, SCCL	General Manager(R&D), The Singareni Collieries Company Limited, Kothagudam Collieries-507101, Bhadrachalam Road Railway Station, Dist- Bhadradi Kothagudem (Telengana State)
133.	13.09.2017	2017-18	2014-15	CNP/3928/2014-15	Scientific investigation and advice to control the fire at Argada Quarry, Central Saunda Colliery, Barka Sayal Area, Ramgarh	The Chief General Manager, Barka Sayal Area, CCL, P.O. – Saunda Dist – Ramgarh Jharkhand-829 126
134.	13.09.2017	2017-18	2016-17	SSP/144/2016-17	Scientific study for monitoring the subsidence of different Strata lying below Dhanbad - Chandrapura railway Line over X Seam fire affected area at Gopal Gareria section of Sendra Bansjora Colliery, BCCL (August'2016 to	The Project Officer, Sendra Bansjora Colliery, Sijua Area, BCCL, P.O.- Bansjora, Dist – Dhanbad (Jharkhand) – 828101

					July'2017)	
135.	13.09.2017	2017-18	2013-14	CNP/3764/2013-14	Scientific investigations and analysis of thermal behavior of coal and determining the incubation periods of coal seams XVI, XVII/XVIB, XIII and XII of Chasnalla Colliery, SAIL- ISP	The Dy.General Manager,Chasnalla Colliery, SAIL-ISP,P.O. –Chasnalla, Dist –Dhanbad, Jharkhand-828135
136.	25.05.2017	2017-18	2016-17	CNP/4492/2016-17	Study and advice for optimization of blast design parameters at Injepalli Limestone Mine of M/s Kesoram Industries Ltd. (Unit-Vasavdatta Cement) to control ground vibration, noise and flyrocks within safe limits for the safety of houses.structures in the periphery of the mine	Kesoram Industries Limited - Cement Division, Unit-Vasavadatta Cement, P.O.- Sedam,Dist-Kalaburagi (Karnataka)
137.	18.09.2017	2017-18	2017-18	CNP/4602/2017-18	Assessment of electrical safety parameters and advice on one no. increased safety Ex 'e' and non-sparking Ex 'n' motor, rated at 1000KW, 6.6KV, 2Pole in Frame size 1MA7712-2 as per IS/IEC:60079-7:2006 & IS/IEC 60079-15:2005 for use in zone2 and Gas Group IIA,IIB & IIC hazardous area	Bharat Heavy Electricals Limited,BHOPAL
138.	18.09.2017	2017-18	2017-18	CNP/4603/2017-18	Assessment of electrical safety parameters and advice on one no. pressurized (Ex'P') motor in 830KW/6 pole/690V in Frame size 1MG7712-6 as per IS/IEC:60079-2:2007 for use in zone-1 & 2 and Gas Group IIA,IIB & IIC hazardous area	Bharat Heavy Electricals Limited,BHOPAL

139.	20.09.2017	2017-18	2016-17	CNP/4404/2016-17	Design of extraction method in 13 and 14 seam with controlled effect on the floor of upper worked out water logged seams at Bhelatand(A) Colliery of Tata Steel	The Head, Bhelatand Amalgamated Colliery, Tata Steel Limited (Jharia Division), P.O.- Bhelatand, Dist -Dhanbad, Jharkhand-828103
140.	20.09.2017	2017-18	2016-17	CNP/4387/2016-17	Scientific study for design of suitable method of extraction in proposed panel nos.21 to 28 in XVI seam below built-up area at Digwadih Colliery of M/s Tata Steel Limited	The Head, Digwadih Colliery, Tata Steel Limited, Jharia Collieries, Jamadoba-828112, Dist -Dhanbad
141.	21.09.2017	2017-18	2017-18	CNP/4592/2017-18	Advice on the use of coal ash from DCP with overburden at Gare Palma IV/1 opencast Mine, Tamnar-Phase II(3)	JSPL, RAIGARH
142.	15.09.2017	2017-18	2016-17	SSP/157/2016-17	Advice on slope stability at Jhamarkotra Rock Phosphate Mine for the year 2016-17, Udaipur, Rajasthan, RSMML	JHAMARKOTRA MINES, RSMML
143.	15.09.2017	2017-18	2015-16	CNP/4278/2015-16	Advice on slope stability of X-Quarry, Sukinda Chromite Mines, Tata Steel	SUKINDA CHROMITE MINES, TATA STEEL
144.	15.09.2017	2017-18	2016-17	SSP/175/2016-17	Advice on slope stability condition by slope monitoring at Mahagiri Mine (Chromite) for the year 2016-17, M/s IMFA, Odisha	MAHAGIRI MINES, IMFA, Jajpur, Odisha
145.	15.09.2017	2017-18	2016-17	CNP/4484/2016-17 & SSP/171/2016-17	Advice on slope stability condition of Sukinda Mines (Chromite) pit and Dump, M/s IMFA, Odisha	SUKINDA MINES (CHROMITE), IMFA
146.	21.09.2017	2017-18	2015-16	CNP/4326/2015-16	Study of Airborne dust collected on filter paper at S.P.Mines, Chitra (ECL)	General Manager, S.P.Mines, ECL, Chitra, Deogarh
147.	21.09.2017	2017-18	2017-18	CNP/4533/2017-18	Performance evaluation of closed circuit compressed oxygen cylinder type breathing apparatus, Model P-30 of JSC DONETSK Mines Rescue Equipment CO., UKRAIN	Industrial Appliances & Technologies, Madhurima House, 83 & 84, Chanditala Main Road, Kolkata - 700053

148.	03.10.2017	2017-18	2015-16	CNP/4317/2015-16	Advice of Rock mechanic instrumentation and stability analysis for SS-3 panel of 4 seam and 3SB-3 panel of 3 seam at Vakilpalli Mine, SCCL	General Manager (R & D)M/s The SCCL Kothagudem Collieries-507101, Dist: Khammam, Telangana
149.	18.10.2017	2017-18	2013-14	CNP/3894/2013-14	Study and advice on soundness of the mechanical integrity of the vital components of man- riding (Chair cars/Chair lift) systems of SCCL	General Manager (R & D)M/s The SCCL Kothagudem Collieries-507101, Dist: Khammam, Telangana
150.	18.10.2017	2017-18	2016-17	CNP/4499/2016-17	Assessment and technical advice on pressurized purge panel, type X as per IS/IEC 60079-2:2007 for use in hazardous area	M/s Pyrotech Electronics Pvt. Ltd.U 2, E 329, Road No.12 M.I.A., Udaipur -313 003
151.	18.10.2017	2017-18	2017-18	SSP/230/2017-18	In-Situ evaluation and advice on the present condition of haulage rope of Pushkar site of Damodar Ropeways & Infra Limited, Rajasthan	Damodar Ropeways & Infra Limited, Vansittart Row, Kolkata
152.	24.10.2017	2017-18	2016-17	CNP/4413/2016-17	Advice on development of paste fill for Mine Backfilling at S.K.Mines, HZL	Sindeswar Khurd Mine, HZL
153.	31.10.2017	2017-18	2016-17	CNP/4498/2016-17	Advice on Rock Mass Rating (RMR) for XII seam (Pathargariya'B' seam) workings at Lohapatti Colliery, West Jharia Area, BCCL	Area Safety Officer, Western Jharia Area, BCCL, Moonidih – 828 129, Dhanbad
154.	01.11.2017	2017-18	2017-18	CNP/4545/2017-18	Advice to assess stability of underground workings from mining- induced subsidence point of view for Surakachhar and Banki Sub-Area of SECL in the vicinity of the proposed East-West Rail Corridor between Gevra Road to Pendra Road for safe movement of trains.	The Chief Project Manager M/s Ircon International Limited, Chhattisgarh Rail Project, IInd Floor , Rama Port, Vyapar Vihar Road, Bilaspur (C.G)-495001
155.	01.11.2017	2017-18	2016-17	CNP/4498/2016-17	Advice on Rock Mass Rating (RMR) for XII seam (Pathargariya'B' seam) workings at Lohapatti Colliery, West	Area Safety Officer , Western Jharia, BCCL, Moonidh-828129, Dhanbad -Jharkhand

					Jharia Area, BCCL	
156.	01.11.2017	2017-18	2013-14	SSP/R/16/2013-14	Evaluation of damage potential of blast induced ground vibration and air overpressure at ratle Hydro Power Project	Project Director, L&T Construction, Ratle Hydro PowerProject, Kishtwar, J&K
157.	06.11.2017	2017-18	2016-17	SSP/140/2016-17	Blast vibration study at Aditya Limestone Mines of M/s Ultratechcement Limited, Shambhupura, chittorgarh, Rajasthan.	M/s Ultratech Cement Limited (Aditya Cement Works) M/s Ultratech Cement Limited (Aditya Cement Works) Adityapuram, Shambapura Chittorgarh, Rajasthan-312622
158.	06.11.2017	2017-18	2017-18	CNP/4597/2017-18	Evaluation and advice on the present condition of rope of cable car system installed at Dreamland Amusement park,Silliguri,West Bengal	M/s Lucky Exports India Private Limited,Bidhan Road,Near Auto Stand,Silliguri -734001(W.B)
159.	07.11.2017	2017-18	2016-17	SSP/135/2016-17	Slope stability study of OB X quarry at Sukinda Chromite Mine, Tata Steel	Sukinda Chromite MineHead (MPP) Kalarangitta, Orissa
160.	13.11.2017	2017-18	2015-16	SSP/64/2015-16	Performance evaluation of multigas detector models altair 4X as per Indian standard R & D sponsored.	The Product line Manager M/s MSA India Region, MSA(India ) Limited Ecostation, Level-16, Plot No.7,Block BP, Salt Lake, Sector V, West Bengal-700091
161.	13.11.2017	2017-18	2015-16	SSP/66/2015-16	Performance Evaluation of Multigas Detector Models Altair 5X and advice on its suitability in all type of mines.	The Product Line Manager M/s MSA India Region, MSA(India) Limited. Ecostation, Level-16, Plot No.7 Block BP, Salt Lake, Sector V, West Bengal-700091
162.	13.11.2017	2017-18	2015-16	SSP/77/2015-16	Performance Evaluation and Repairing of Defective Methanometer, Satgram Area, ECL Sponsored (Contract Research)	The General Manager M/s Eastern Coalfields Limited,Satgram Area, PO-Devchandnagar, Dist:

						Burdwan (W.B)
163.	13.11.2017	2017-18	2015-16	SSP/90/2015-16	Performance evaluation of portable Methane Gas Monitor, Model Telgas 1000AR	M/s. Teledyne-Ray Administrative and Sales Office, "Srikunj" (4th Floor), 238, B.T. Road, Kolkata - 700036
164.	14.11.2017	2017-18	2016-17	CNP/4450/2016-17 & SSP/123/2016-17	1. Advice on the present condition of the vital components at man-riding (Chair cars/Chairs lift) systems of SSCL (Project No. CNP/4450/2016-17) 2. In Situ Study on the present condition of the vital components at man-riding (Chair cars/Chair lift) systems of SCCL (SSP/123/2016-17)	General Manager (R&D), The Singareni Collieries Company Limited, Kothagudam Collieries- 507101 Bhadrachalam Road Railway Station, Dist- Khammam (Telengana State)
165.	22.11.2017	2017-18	2015-16	SSP/75/2015-16	Advice for optimisation of blast design parameters at Sindesar Khurd Mine to control blast vibration within safe limits at surface and houses/structures of the adjacent villages	M/s. Hindustan Zinc Limited, Executive - Commercial, Sindesar Khurd Mines, Post.- Dariba-313211, Dist.- Rajsamand (Rajasthan)
166.	27.11.2017	2017-18	2017-18	SSP/229/2017-18	Environmental quality monitoring mitigative measures and related advice for kathautia Open Cast Coal Mines, Daltonganj, Jharkhand	M/s. Hindalco Industries Ltd., Old Ranchi Road, Near Durga Petrol Pump, Redma, Daltonganj, Palamu, Jharkhand-822101
167.	27.11.2017	2017-18	2017-18	SSP/203/2017-18	Geo-technical studies of rock core samples of BH# SLB/MM/019(P-16) from Salanpur B Block, Raniganj Coal Field and advice thereof	GM Geology CMPDI, RI-I, Asansol
168.	27.11.2017	2017-18	2017-18	SSP/204/2017-18	Geo-technical studies of rock core samples of BH# DHL/MD/002(P-56). Dhulia Coal Block, Rajamahar Coal Field and Advice thereof	GM Geology CMPDI, RI-I, Asansol



169.	27.11.2017	2017-18	2017-18	SSP/205/2017-18	Geo-Technical studies of rock core samplesw of BH# MDPMP-008 (P-49). Mandar Parvat Block, Hura Basin, Rajmahal Coal Field and advice thereof.	GM Geology CMPDI, RI-I, Asansol
170.	27.11.2017	2017-18	2017-18	SSP/206/2017-18	Geo-technical studies of rock core samples of BH# CMWA-15 of West of Ashoka Block of North Karanpura Coal Field and advice thereof.	Assistant Manager Geology CMPDI, Hazaribag Camp, RI-3, Ranchi
171.	27.11.2017	2017-18	2017-18	SSP/209/2017-18	Geo-technical studies of rock core samples of BH# MSSL-115 of Shahdol Block (Non-Cil) of Sohagpur Coal Field and advice thereof	General Manager (Exploration) CMPDIL, RI-V Bilaspur, Chattisgarh
172.	27.11.2017	2017-18	2017-18	SSP/210/2017-18	Geo-technical investigation to evaluate strength characteristics of rock core samples from BH# MCMM-04 and MVSM-05 of Harur Molybdenum Project, Tamilnadu and advice thereof	Dy. GM (Exploration) M/s. MCL, Nagpur, Maharashtra
173.	27.11.2017	2017-18	2017-18	SSP/211/2017-18	Geo-technical studies on rock core samples of BH# MMD-25 and MMD- 32 from Dip Side of Meenaksh Coal Block, IB River Valley Coal Field and advice thereof	HOD (Business Development Commercial) M/s. MECL, Nagpur
174.	27.11.2017	2017-18	2017-18	SSP/213/2017-18	Geo-technical studies on rock core samples of BH# ATRE-07 (P-14) from Reonti East Block, Tatapani Ramkola Coal field and advice thereof	General Manager (Exploration) CMPDIL, RI-V Bilaspur, Chattisgarh
175.	27.11.2017	2017-18	2017-18	SSP/214/2017-18	Geo-technical studies of rock core samples of BH# CKBI-112 of Bhilai Block of Korba Coal Field and advice thereof	General Manager (Exploration) CMPDIL, RI-V Bilaspur, Chattisgarh
176.	27.11.2017	2017-18	2017-18	SSP/215/2017-18	Geo-technical studies of rock core samples of BH# GSBN-58 of Bicharpur North Block (Non-Cil) of Sohagpur Coal Field and advice thereof.	General Manager (Exploration) CMPDIL, RI-V Bilaspur, Chattisgarh

177.	27.11.2017	2017-18	2017-18	SSP/216/2017-18	Geo-technical studies of rock core samples of BH# SPNG-37 of Gonda Coal Block, North Karanpura Coal field and advice thereof	HOD (Exploration) CMPDIL, RI-III, CMPDIL, Ranchi
178.	27.11.2017	2017-18	2017-18	SSP/217/2017-18	Geo-technical studies of rock core samples of BH# CMDV-17 of DVC Bermo, East Bokaro Coal Field and advice thereof	HOD (Exploration) CMPDIL, RI-III, CMPDIL, Ranchi
179.	27.11.2017	2017-18	2017-18	SSP/218/2017-18	Geo-Technical Studies of Rock Core Samples of BH# TEPE-09/P-07 of Pundi East Block, West Bokaro Coal Field and advice thereof	HOD (Exploration) CMPDIL, RI-III, CMPDIL, Ranchi
180.	27.11.2017	2017-18	2017-18	SSP/219/2017-18	Geo-technical studies of rock core samples of BH# CMRWB-62 of Ramgarh Block II, Ramgarh Coal Field and advice thereof	HOD (Exploration) CMPDIL, RI-III, CMPDIL, Ranchi
181.	27.11.2017	2017-18	2017-18	SSP/226/2017-18	Geo-technical studies of rock core samples of BH# ASAE-53 of Arjuni East Block (Non-Cil), Sohagpur Coal Field and advice thereof	M/s. GM (Exploratio) CMPDIL, RI-V, Bilaspur, Chattisgarh
182.	27.11.2017	2017-18	2017-18	SSP/227/2017-18	Geo-technical studies of rock core samples of BH# CSBE-72 of Bicharpur East block, Sohagpur Coal Field and advice thereof	M/s. GM (Exploratio) CMPDIL, RI-V, Bilaspur, Chattisgarh
183.	27.11.2017	2017-18	2017-18	SSP/228/2017-18	Geo-technical studies of rock core samples of BH# MMPA-59, West of Basin Phatehpur A Block, Man Raigarh Coal Field and advice thereof	M/s. GM (Exploratio) CMPDIL, RI-V, Bilaspur, Chattisgarh
184.	27.11.2017	2017-18	2017-18	SSP/212/2017-18	Geo-technical studies on rock core samples of BH# MMB-03 and MMB-32 from Meenakshi B Block, Meenakshi Coal Block, IB River Valley Coal field and advice thereof	HOD (BD and C) M/s. MECL, Nagpur

185.	27.11.2017	2017-18	2016-17	SSP/117/2016-17	Feasibility study of ash filling in abandoned coal mine using ash from Lanco Power Limited.	Lanco Power Limited Lanco Power Limited Plot No. 397 Udyog Vihar, Phase-III, Gurgaon-122016
186.	28.11.2017	2017-18	2016-17	CNP/4498/2016-17	Advice one Rock Mass Rating(RMR )for XVI Top Seam Workingsat Moonidih Colliery, Western Jharia Area,BCCL	Area safety Officier,Western Jharia Area,BCCL,P.O-Moonidih-828129,BCCL Dist-Dhanbad
187.	04.12.2017	2017-18	2017-18	CNP/4616/2017-18	Advice on use of coal ash from DCPD with overburden at Gare Pelma IV/1 opencast mine, Tamnar- Phase II (4)	The Head (Environment) DCPD, JSPL, CG
188.	04.12.2017	2017-18	2016-17	CNP/4518/2016-17	Advice on slope stability condition of Rampura Agucha mine, Hindustan Zinc Ltd., (HZL)	Dr. P.K Rajmeny,AVP(Rock Mech),Rampu Agucha Mine,P.O:-Augcha-311029,Dist:-Bhilwara,Rajasthan
189.	05.12.2017	2017-18	2016-17	CNP/4474/2016-17	Scientific study and Advice for ascertaining the thickness of crown pillar below 85mRL up to -395mRL at different levels with stope height of 50m at mahagiri mines(Chromite) in Sukinda Valley of M/s IMFA Limited.	Mr.M.J.RAJU,DGM-Geology,INDIAN METALS & FERRO ALLOYS LTD.,IMFA Building,Rasulgarh,Bhubaneshwar -751010
190.	05.12.2017	2017-18	2014-15	SSP/38/2014-15	Detailed parametric study of bulk head design for various water levels in open pit at Rampura Agucha Mine, HZL.	M/s HZL Commercial Dept, Rampura Agucha Mine
191.	06.12.2017	2017-18	2017-18	SSP/207/2017-18 & CNP/ 4564/2017-18	Generation of physico-mechanical properties as suggested by Jharia Collieries,Tata Steel Limited of BH#TJS-224-13	M/s Tata Steel Limited (JhariaDivision),Jamadoba, Dist. Dhanbad,Jharkhand-828112
192.	07.12.2017	2017-18	2017-18	CNP/4530/2017-18	Advice to conduct blasts beyond 50m from structures/dwellings/hutments,villages and 25m away from PWD/village road under regulation 164(I-B) of MMR 1961 for Naubasta & Bankuiyan Lime Stone	M/s Jaiprakash Associates Limited,Jaypee Rewa Plant,Jaypee Nagar,Rewa,M.P-486450

					Mines	
193.	11.12.2017	2017-18	2015-16	SSP/83/2015-16	Assessment of Flame proof syste design for E.O.T cranes of 2T capacity span pendant operated 14 Nos.(Fourteen),5T capacity monorail 02 Nos.(Two)and 5T capacity EOT cranes 04 Nos.(Four)for use in Gas Group IIA& IIB hazardous Area.	M/s Dinesh Enterprises,401/A,Vurndavan,Mur bad Road,Kalyan-421304
194.	14.12.2017	2017-18	2012-13	CNP/3503/2012-13	Study and evaluation of bulk explosives,cartridge explosives and blasting accessories from different projects of Northern Coalfields Limited.	Chief General Manager(Production),Northern Coalfields Limited,Singrauli,M.P-486889
195.	14.12.2017	2017-18	2012-13	CNP/3464/2012-13	Advice on quality assessment of explosive and blasting accessories to improve productivity and safety .	Chief General Manager(Production),Mahanadi Coalfields Limited,Jagriti Vihar,Burla,Sambalpur,Odisha -768020
196.	14.12.2017	2017-18	2013-14	CNP/3827/2013-14	Advice and assessment of quality of explosives and blasting accessories to improve productivity and safety in Excavation works	Chief General Manager(Production),Mahanadi Coalfields Limited,Jagriti Vihar,Burla,Sambalpur,Odisha -768020
197.	20.12.2017	2017-18	2015-16	SSP/110/2015-16	Investigation into genesis of methane accumulation in the D-12 longwall face in XVI top seam of Moonidih Colliery.	The General Manager(Western Jharia Area),Bharat Coking Coal Limited,P.O:Moonidh,Dist:-Dhanbad,Jharkhand-828129
198.	20.12.2017	2017-18	2015-16	CNP/4371/2015-16	Advice for improvement in ventilation in longwall D-12 panel in XVI top seam of Moonidih Colliery.	The General Manager(Western Jharia Area),Bharat Coking Coal Limited,P.O:Moonidh,Dist:-Dhanbad,Jharkhand-828129

199.	20.12.2017	2017-18	2017-18	CNP/4537/2017-18	Analysis of root cause of incidence of fire in coal conveyor at Talwandi Sabo Power Ltd. Punjab.	The Head Commercial,TALWANDI SABOPOWER LTD, Village:Banawala,Mansa(Punjab), Pin code-151302
200.	20.12.2017	2017-18	2016-17	CNP/4409/2016-17	Scientific advice to control open fire below 61L at Kapildhara Colliery, SECL and safe reopening and recovery of sealed off area.	Sub-Area Manager, Kurja Area,SECL,P.O-Bijuri,Dist-Anuppur,MP-481440
201.	22.12.2017	2017-18	2015-16	SSP/88/2015-16	Instrumentation plan and strata monitoring during extraction of pillars in the proposed CMP 9 Panel [Sub panels CMP-9A(1),CMP-9A(2) and CMP-9A(3)] using continuous Miner technology at VK-7 Incline, Kothagudem area, SCCL.	The General Manager (R &D),The Singareni Collieries Limited, Kothagudem Collieries,Bhadrachalam Road Rly.Station(SC Rly),Dist:Bhadradri Kothagudem,Telangana-507101
202.	26.12.2017	2017-18	2013-14	CNP/3910/2013-14	Advice and assessment on explosives quality and blasting and blasting accessories at Tata Ore Mines and Quarries	General Manager,Ore Mines and Quarries,Tata Steel Limited,Noamundi-833217,West Singhbhum(Jharkhand)
203.	26.12.2017	2017-18	2012-13	CNP/3504/2012-13	Study and Evaluation of bulk explosives,cartridge explosives and blasting accessories from different projects of Northern Coalfields Limited.	Chief General Manager(Production),Northern Coalfields Limited,Singrauli,M.P-486889
204.	27.12.2017	2017-18	2015-16	CNP/4316/2015-16	Advice on use of bottom ash for underground stowing at RK-7 Incline, SCCL.	The General Manager (R &D), Kothagudem Collieries, Bhadrachalam Road Rly.Station(SC Rly), Dist:Bhadradri Kothagudem,Telangana-507101
205.	28.12.2017	2017-18	2017-18	CNP/4615/2017-18	Advice on slope stability of final Dip side highwall slope at Medapalli OCP, SCCL.	The General Manager (R &D), Kothagudem Collieries, Bhadrachalam Road Rly.Station(SC Rly), Dist:Bhadradri Kothagudem,Telangana-507101

206.	28.12.2017	2017-18	2014-15	CNP/4149/2014-15	Advice for depillaring of R- VI seam with deployment of continuous Mmner including support design, considering increased height and width of extraction at Khottadih Colliery, ECL	Dy.General Manger/Agent,Office of the Agent, Khottadih Colliery,pin-713378 P.O. - Kottadih, Dist. - Burdwan
207.	28.12.2017	2017-18	2014-15	CNP/4116/2014-15	Studies on gap sensivity of low density Ammonium Nitrate Prill.	M/s Deepak Fertilisers and Petrochemicals corp. Ltd.,Sai Hira,Survey No. 93,Mundhwa,Pune-411036
208.	28.12.2017	2017-18	2012-13	CNP/3586/2012-13	Advice on quality assessment of explosives and blasting acessories to improve productivity and safety.	Mahanadi Coalfields Limited ,Jagriti Vihar,Burla ,Sambalpur-768020 (Orissa)
209.	03.01.2018	2017-18	2014-15	CNP/4158/2014-15	Advice and suggestion on detonation sensitivity and shock wave detonation of Ammonium Nitrate Prill	Deepak fertilisers and Petrochemicals Corp. Ltd.,Sai Hira, Survey No. 93, Mundhwa , Pune - 411036
210.	03.01.2018	2017-18	2017-18	CNP/4546/2017-18	Scientific study and advice to control fire in W1 panel and early resumption of production from Mohan Colliery, Kanhan Area, WCL.	Area General Manager,KanhanArea, WCL, Dungaria, Chindwara-480553
211.	05.01.2018	2017-18	2010-11	CNP/2645/2010-11	Study on Improvement and Modification of Small diameter Explosives suitable for Gassy and Dusty Mines.	M/s IDEAL Industrial Explosives Ltd.,1st Floor, Amardeep Complex, Akbar Road, Tadbund, Secunderabad - 500009 (Andhra Pradesh)
212.	05.01.2018	2017-18	2014-15	CNP/4125/2014-15	Testing and analysis of physico-mechanical properties for proto type steel cogs 30 tonne.	Project Officer,Regional Workshop(B),Bhurkunda,CCL,Bh urkunda,Ramgarh-829135
213.	09.01.2018	2017-18	2017-18	SSP/240/2017-18	In situ non-destructive study and advice on the present condition of track, haulage ropes of bi-cable Joshimath- Auli ropeway, haulage rope of Chair lift, haulage ropes of two Ski Lift (Old and New) of Garhwal Mandal Vikas Nigam	General Manager (Projects),Garhwal Mandal VikasNigam Ltd (GMVn), 74/1,Rajpur Road,Dehradun,Uttarakhand-248001

					Ltd (GMVN), Joshimath.	
214.	10.01.2018	2017-18	2016-17	CNP/4487/2016-17	Assessment and technical advice on partially purged Control Panel as per IS/IEC 60079:2-2007 and NFPA-496-2008 suitable for use in Zone 1 & 2 and Gas Group IIC hazardous area.	M/s Electronics Instrumentation & Control Pvt. Ltd., 56, Panchratna Industrial Estate, Sarkhej-Bavia Road, Taluka: Sanand Dist: Ahmedabad- 382213 (Gujarat)
215.	12.01.2018	2017-18	2010-11	CNP/2844/2010-11	Studies and improvement of small diameter explosive suitable gassy and dusty mines.	M/s Special Blast Limited, F-105, First Floor, Wallfort Ozone, Near Fafadih Chowk, Raipur-492001 (Chhatisgarh)
216.	19.01.2018	2017-18	2016-17	CNP/N/4445/2016-17	Salinity Ingress Study With Special Reference to Hydrological Regime in and around Narmada Cement-Jafarabad Works (NCJW), UltraTech Cement Limited, Village-Babarkot, Taluka-Jafarabad, Dist-Amreli (Gujarat)	M/s Ultratech Cement Limited Unit-NCJW Village Babarkot: Taluka-Jafarabad Dist: Amreli, PIN-365540, Gujarat.
217.	22.01.2018	2017-18	2017-18	CNP/4625/2017-18	Evaluation and advice on the present condition of haulage rope of Deattachable grip mono-cable passenger ropeway at Trikut pahar, Deoghar, Jharkhand.	M/s Damodar Ropeways & Infra Road 1/A, Vansittart Row Kolkata-700001
218.	23.01.2018	2017-18	2015-16	SSP/82/2015-16	Scientific study of strata movement during widening and heightening of existing galleries and depillaring of CM panels A1-A and A1-B of No. 1 at GDK-11 Incline mine, RG-1 area, SCCL through underground instrumentation and monitoring.	General Manager (R&D) M/s The SCCL Kothagudem Collieries-507101 Bhadrachalam Road Railway Station Khammam Dist Telangana
219.	24.01.2018	2017-18	2017-18	CNP/4608/2017-18	Advice on the blast parameters to optimise the charge per delay to maintain the level of ground vibration and Noise	M/s. J.K. Cement Works, Kailash Nagar - 312617 Nimbahera,

					within the safe limit as per DGMS Circular considering the production schedule of Murlia Block of JK Cement Limestone Mine, Nimbahera.	Dist. - Chittorgarh (Rajasthan)
220.	25.01.2018	2017-18	2017-18	CNP/4610/2017-18	Advice on feasibility of deep stone mining of a small scale dolerite stone deposit through mathematical modeling and computer simulation for M/s CEMMIX structural Pvt. Ltd. at Baliapur Mouza, Pachimbardwan Dist, West Bengal.	M/s CEMMIX Structural Pvt. Ltd. Block CE, Plot 218 ii floor, Sector-1, Salt Lake city, Kolkata-700064
221.	31.01.2018	2017-18	2016-17	SSP/121/2016-17	Advice for safe depillaring of the panel LK-7 of Lower Kajora seam at Central Kajora Colliery by cable bolting based instrumentation and monitoring.	Sr. Manager (M) M/s Eastern Coalfields Limited Central Kajora Colliery Kajoragram, Dist: Burdwan, West Bengal
222.	31.01.2018	2017-18	2016-17	SSP/122/2016-17	Advice for safedepillaring of the panel LK-8 of Lower Kajora seam at Central Kajora Colliery by cable bolting based depillaring method through underground monitoring.	Sr. Manager (M) M/s Eastern Coalfields Limited Kajora Area PO- Kajoragram Dist: Burdwan, West Bengal
223.	31.01.2018	2017-18	2016-17	SSP/118/2016-17	Advice for safe depillaring of the panel LK-6 of Lower Kajora seam at Central Kajora Colliery by cable bolting based depillaring method through underground instrumentation and monitoring.	Sr. Manager (M) M/s Eastern Coalfields Limited Central Kajora Colliery, Kajora Area, ECL, PO-Kajoragram, Dist:- Burdwan, West Bengal
224.	02.02.2018	2017-18	2014-15	CNP/4188/2014-15	Assessment of status of fire along main JC railway line and advice to deal with fire during mining operation (OCP) in XV, XIV & XIII seam at Kankanee Colliery.	Project officer, Kankanee Colliery, BCCL, Sijua Area, Sijua, Dhanbad- Jharkhand-828101
225.	05.02.2018	2017-18	2015-16	SSP/61/2015-16	Scientific study for formulation of guidelines on ventilation procedures for continuous miner section in R-VI seam of Jhanjra Project Colliery	General Manager, Jhanjra Area, ECL, P.O. -Jhanjra (B.O.) Dist – Burdwan



226.	15.02.2018	2017-18	2017-18	CNP/4640/2017-18 & SSP/249/17-18	Geo-technical studies of rock core samples of BH # SMPB-99 of West of Basin Phatehpur B Block, Mand Raigarh Coalfield and advice thereof.	General Mnager (Exploration),RI-V,SECL Complex,Seepat Road,Bilaspur,Chhattisgarh-495006
227.	15.02.2018	2017-18	2016-17	CNP/4498/2016-17	Advice on Rock Mass Rating (RMR)for XVI top seam workings at Moonidih Colliery andXII seam workings at Lohapati Colliery,West Jharia Area,BCCL.	Area safety Officer,Western JhariaArea ,Moonidih,BCCL, Dist- Dhanbad-828129
228.	15.02.2018	2017-18	2015-16	SSP/101/2015-16	Monitoring of drilling and blasting work at Gagal Limestone Mine, M/s ACC Ltd.	Mines ManagerM/s ACC Ltd., Gagal Limestone MinePO- Barmana Dist: Bilaspur, 174013
229.	28.02.2018	2017-18	2011-12	CNP/3010/2011-12	Study and Advice on Ventilation System of underground mines of Korba Area ,South Eastern coalfields Limited(Part I:Dhelwadi U/G Mine,Part II:Singhali U/G Mine,Part III:Bagdeva U/G Mine).	Sub Area Manager,DSB Sub Area,Korba Area,SECL,Katghora-495445,Dist- Korba,Chhattisgarh
230.	28.02.2018	2017-18	2016-17	CNP/4519/2016-17	Advice on slope stability condition at AC-DE Quarry, OMC, Odisha	The Regional Manager M/s Odisha Mining Corporation Limited OMC, PO. F.C. Plant Jajpur, Orissa.
231.	28.02.2018	2017-18	2016-17	CNP/4519/2016-17 & SSP/186/2016-17	Advice on slope stability condition of active mine and dump slopes of D- Quarry, OMC, Odisha.	The Regional Manager M/s Odisha Mining Corporation Limited OMC, PO. F.C. Plant Jajpur, Orissa.
232.	12.03.2018	2017-18	2017-18	CNP/4605/2017-18	In-Situ investigation and advice on the present condition of four nos of track ropes and two nos. of haulage ropes of passenger cable car aerial ropeway installation of M/s Timber Trail, Asia Resorts Limited, Parwanoo (H.P.) – Two visits	Ropeway Incharge, Timber Trail,Asia Resorts Limited,Parwanoo-173220, Himachal Pradesh

233.	12.03.2018	2017-18	2017-18	CNP/4636/2017-18	Evaluation and advice on the present condition of haulage rope Shri Naina Deviji monocable ropeway at Shri Naina Deviji, H.P	Damodar Ropeways & Infra Limited, Vansittart Row, Kolkata
234.	12.03.2018	2017-18	2017-18	CNP/4631/2017-18	Evaluation and advice on the present condition of haulage rope of Jakhu ropeway at Shimla, H.P.	Shri C.K.Chhetri, Manager Operation and Maintenance, M/sJagson International Limited (Jakhu Ropeway Project),Near U.S.Club, Shimla-171 001 , Himachal Pradesh
235.	12.03.2018	2017-18	2017-18	CNP/4652/2017-18	Stability test of CCL, DAV School building for construction of one additional floor on the top of the ground floor.	The Chief Engineering (M)/ Agent The Chief Engineering (M)/ Agent CCL, Giridih ProjectBeniadih-815311 Giridih
236.	19.03.2018	2017-18	2017-18	CNP/4617/2017-18	Advice to redesign extraction sequences, ribs, snooks and support system with CM deployment in panel 11 at Jhanjra, ECL	Dy.General Manager,Office of the Dy.General Manager,Jhanjra Area, ECL, P.O. –Laudaha, Dist – Burdwan (W.B.) - 713385
237.	19.03.2018	2017-18	2017-18	CNP/4620/2017-18	Design of extraction pattern for developed pillars of panel CMP-10 Sub panels 10A(1), 10A(2) and 10A(3) in king seam lying below caved goaf of top seam using CM Technology at VK- 7 Incline, Kothagudem Area, SCCL.	General Manager(R&D),The Singareni Collieries Company Limited, Kothagudam Collieries-507101, Bhadrachalam Road Railway Station,Dist-Bhadradi Kothagudem (Telengana State)
238.	23.03.2018	2017-18	2017-18	CNP/4528/2017-18	Advice on Scientific study for extraction of thick seam as well as suitable methods for systematic liquidation of areas standing on pillars at Orient Mine No.1&2, Orient Area, MCL.	General Manager, Orient Area,MCL, P.O. – Brajrajnagar, Dist –Jharsuguda (Odisha) - 768216
239.	23.03.2018	2017-18	2017-18	SSP/246/2017-18	In situ non-destructive study and advice on the present condition of winding ropes in Service shaft and Production shaftof	Business Manager, CC3-India China Coal No.3 Mining (India)Private Limited,

					China Coal No.3 Mining (India) Private Limited.	P.No.213A, MLA Colony, Banjara Hills, Telengana, Hyderabad– 500 034
240.	31.03.2018	2017-18	2014-15	CNP/N/4184/2014-15	Scientific Study for determination of suitable method of blasting without affecting structures and habitats of nearby village at RGOC-III, Phase-II, SCCL	GM(R&D) Singreni Collieries, Kothagudem Collieries, Dist - Khammam-507101 (T.S)
241.	04.04.2018	2018-19	2017-18	CNP/4647/2017-18	Advice on proposed overall slope angle of both Band I & II ore bodies at Sukinda Mines (Chromite), IMFA	Senior Manager M/s IMFA Building Bhubaneswar - 751010 Odisha
242.	06.04.2018	2018-19	2017-18	CNP/4642/2017-18	Precise measurement, 3D modeling of coal heap and coal volume computation at Brahmadiha OCP of castron mining limited	Directorate of enforcement, govt.of india, ranchi sub zonal office, pee-pee compound, ranchi
243.	16.04.2018	2018-19	2017-18	CNP/4551/2017-18	Advice on optimum slope design of pits and Dumps at South and North blocks of Donimalai Iron Ore Mines, NMDC	Jt General Manager M/s NMDC Ltd., PO- Donimalai Taluk- Sandur, Dist-Bellary Karnataka-583118
244.	14.04.2018	2018-19	2017-18	SSP/N/232/2017-18	Geo-hydrological studies for Pandridalli and Rajhara Pahar Mining lease (Rajhara Mechanized Mine) of Bhilai Steel Plant, Dalli Rajhara, Dist- Balod, Chattisgarh.	Dy. General Manager (Environment) Iron Ore Complex, Rajhara Mechanized Mine BSP-Sail, PO- Dalli- Rajhara Dist- Balod (C.G)
245.	14.04.2018	2018-19	2016-17	CNP//4473/2016-17	Proof Checking of Detailed Design and Drawings of Z-Morh Tunnel in J&K	IL&FS Transportation Networks Ltd Design and Development Unit 402 , Shivalik II , Near Shivaranjanani Cross Roads  132 Ring Road, Satellite, Ahmedabad 380015

246.	16.04.2018	2018-19	2017-18	CNP/4544/2017-18	Advice for prevention and control of spontaneous combustion/fire in coal heap at Talwandi Sabo Power Limited (TSPL 3x660 MW), Punjab	M/s Talwandi Sabo Power Ltd., Village- Banwala, Mansa-Talwandi Sabo Road, Mansa, Punjab-151302
247.	19.04.2018	2018-19	2016-17	CNP/4494/2016-17	Scientific investigation and studies for advising the incubation period of XIV-coal seam of Jitpur colliery (SAIL-ISP)	Project Officer, N/Jitpur Colliery, Steel Authority of India Limited, P.O. – Jitpur, Dist-Dhanbad - 828309
248.	20.04.2018	2018-19	2017-18	CNP/4606/2017-18	Analysis of airborne dust collected on Filter paper at Nigahi Project (NCL) .	Safety Officer, Nigahi Project, P.O. – Nigahi, Dist –Singrauli (M.P.) –486 884
249.	23.04.2018	2018-19	2017-18	CNP/4653/2017-18	Advice to design alternative method of depillaring in seam-II of Gare Palma IV/5 underground coal mines, Raigarh, with an aim to have no adverse mining induced subsidence effect on surface	Vice President-Mines, M/s Hindalco Industries Limited, Gare Palma Mines, Vill. & PO –Milupar, Tehsil – Tamnar, Dist –Raigarh, (Chhattisgarh), PIN-496107
250.	23.04.2018	2018-19	2017-18	CNP/4607/2017-18	Advice on the control blasting at Pathariya Limestone Mine beyond 150m from public structures	Shri Radhe Shyam Ray, Chief Manager (Mining), M/s Jamul Cement Works, ACC Limited, P.O.-जामुल/Jamul Dist –Durg (Chhattisgarh) PIN – 490 024
251.	26.04.2018	2018-19	2016-17	CNP/4452/2016-17	In-situ investigation and advice on the present condition of haulage rope of D.R.V. Passenger Ropeway at Darjeeling, West Bengal – Two visits	DGM (Marketing), Conveyor & Ropeway Services Pvt. Ltd., 75-C, Park Street, 6 <sup>th</sup> Floor, Kolkata -700016
252.	04.05.2018	2018-19	2018-19	SSP/279/2018-19	Assessment of Physico-mechanical properties of BH# BBD/MM/014 (P- 12) of Barul Bagdiha Block, Raniganj Coalfield.	M/s CMPDIL M/s CMPDIL RI-1, G.T. Road West Asansol-713304
253.	04.05.2018	2018-19	2018-19	SSP/280/2018-19	Assessment of Physico-mechanical properties of BH# BBD/MM/012 (P- 83) of Barul Bagdiha Block, Raniganj	M/s CMPDIL M/s CMPDIL RI-1, G.T Road West, Asansol-713304

					Coalfield.	
254.	11.05.2018	2018-19	2016-17	SSP/183/2016-17	Study and evaluation of seismographs for their reliable operations and advice on technical aspects for accurate vibration recordings.	M/s. Indian Explosives Pvt. Ltd., Orisa
255.	11.05.2018	2018-19	2017-18	SSP/200/2017-18	Study and evaluation of seismographs for their reliable operations and advice on technical aspects for accurate vibration recordings.	Black Diamond Explosive Pvt. Ltd. Surya Auto Campus, Dhansar, Dhanbad-828106
256.	11.05.2018	2018-19	2017-18	CNP/4618/2017-18	Advice on assessment of strata behaviour and susceptibility to spontaneous heating during extraction of B1 panel in R VI seam at Khottadih Colliery, ECL	Dy.General Manager/Agent, Khottadih Colliery, ECL, Office of the Agent, P.O.-Khottadih, Dist-Burdwan (W.B.) PIN – 713378
257.	21.05.2018	2018-19	2015-16	SSP/67/2015-16	Study on soundness of mechanical integrity of vital components of MOIL, Nagpur through non-destructive evaluation	Sr.Dy.General Manager(Mech), MOIL Limited, MOIL Bhawan, A-1, Katol Road, Nagpur-440 013
258.	21.05.2018	2018-19	2017-18	CNP/4627/2017-18	Advice on electrical safety parameters of one no. increased safety Ex 'e' and non-sparking Ex 'n' motor, rated at 1050KW, 6.6 KV, 2 pole in frame size: 1SD7450-2 as per IS-IEC 60079-7:2006 & IS/IEC 60079-15:2005 for use in zone 2 and gas group IIA, IIB & IIC hazardous area.	Assistant Engineer M/s Bharat Heavy Electrical Limited. Industrial machine sales division Piplai, Bhopal - 462022 (M.P)
259.	21.05.2018	2018-19	2017-18	CNP/4656/2017-18	Advice on electrical safety parameters of one no. Increased safety Ex 'e' and non-sparking Ex 'n' motor, Rated at 3210KW, 6.6 KV, 4 Pole in frame size: 1SJ7718-4 as per IS/IEC 60079-7: 2006 & IS/IEC 60079-15:2005 for use in	M/s Bharat Heavy Electrical Limited M/s Bharat Heavy Electrical Limited Industrial machine Sales Division Annexe, Block-II

					zone 2 and gas group IIA,IIB & IIC hazardous area	Pipalni, Bhopal-462022 (M.P)
260.	21.05.2018	2018-19	2017-18	SSP/273/2017-18 & CNP/4613/2017-18	Assessment of electrical safety parameters and advice on one no. Increased Safety Ex'e' and Non-Sparking Ex 'n' Motor , Rated at 225KW, 6.6KV, 2 Pole in Frame size: 1MA7502-2 as per IS/IEC 60079-7: 2006 & IS/IEC 60079-15:2005 for use in zone 2 hazardous area.	M/s Bharat Heavy Electricals Limited M/s Bharat Heavy Electricals Limited Block-II annexe Easter Wining, Second Floor, Piplani, Bhopal-462022
261.	21.05.2018	2018-19	2017-18	SSP/272/2017-18 & CNP/4612/2017-18	Assessment of electrical safety parameters and advice on pressurized (Ex'p') Motor Rated at 2440 KW, 6.6KV, 4 pole in frame size 1SB7718-4 as per IS/IEC: 60079-2 : 2007 for use in zone 1 & 2 for gas group IIA/IIB/IIC hazardous areas.	M/s Bharat Heavy Electricals Limited M/s Bharat Heavy Electricals Limited Block-II annexe Easter Wining, Second Floor, Piplani, Bhopal-462022
262.	21.05.2018	2018-19	2017-18	SSP/271/2017-18 & CNP/4609/2017-18	Assessment and technical advice on One No. pressurized Purge Panel - type X as per IS/IEC 60079-2:2007 and NFPA 496-2013 for use in zone 1 & 2 for gas group IIC hazardous area	M/s. IRIS Automation Pvt. Ltd., Plot No. 164/6 and 7, Santej - Vasdsar Road, Santej - 382721, Gujarat
263.	21.05.2018	2018-19	2017-18	SSP/268/2017-18 & CNP/4598/2017-18	Assessment and Advice for suitability of Electrical equipment installed in Zone 2 hazardous areas of Ankleshwar asset of ONGC	M/s. ONGC Ankleshwar (Gujarat)
264.	21.05.2018	2018-19	2017-18	SSP/270/2017-18 & CNP/4603/2017-18	Assessment of electrical safety parameters and advice on one no. pressurized (Ex'P') motor in 830KW/6 pole/690V in Frame size 1MG7712-6 as per IS/IEC:60079-2:2007 for use in zone-1 & 2 and Gas Group IIA,IIB & IIC hazardous area	Bharat Heavy Electricals Limited, BHOPAL

265.	21.05.2018	2018-19	2017-18	SSP/269/2017-18 & CNP/4602/2017-18	Assessment of electrical safety parameters and advice on one no. increased safety Ex 'e' and non-sparking Ex 'n' motor, rated at 1000KW, 6.6KV, 2Pole in Frame size 1MA7712-2 as per IS/IEC:60079-7:2006 & IS/IEC 60079-15:2005 for use in zone2 and Gas Group IIA,IIB & IIC hazardous area	Bharat Heavy Electricals Limited, BHOPAL
266.	28.05.2018	2018-19	2018-19	CNP/4679/2018-19	Scientific study for geotechnical property of rock at Nimcha Colliery, Eastern Coal Field Ltd and advice thereof	Cuprum Bagrodia Ltd., Kolkata
267.	28.05.2018	2018-19	2017-18	CNP/4657/2017-18	Advice on use of coal ash from DCP with overburden at Gare Palma IV/1 opencast Mine, Tamnar-Phase III(1)	M/s Jindal Steel & Power Limited M/s Jindal Steel & Power Limited Dongamahua Captive Power Plant(4x135 MW) Dongamahua, Tamnar, Raigarh(CG), 496107
268.	28.05.2018	2018-19	2017-18	CNP/4531/2017-18	Advice on commissioning of backfilling plant and design of backfill system for slope block 05 at Mahagiri Mines, Indian Metals and Ferro Alloys Limited	Sr. GM-SCM M/s Indian Metals and ferro Alloys Limited. PO- Kalipani Dist-jaipur, Odisha
269.	31.05.2018	2018-19	2017-18	CNP/4566/2017-18	Geotechnical studies of rock core samples from Khottadih Colliery u/g borehole, Eastern Coalfield Limited and advice thereof	Dy GM (M)/ Agent Eastern Coalfields Ltd., Khottadih Colliery Pandaveswar Area, P.O.- Khottadih, Dist - Burdwan (W.B.) Pin 713378
270.	07.06.2018	2018-19	2016-17	SSP/124/2016-17	In-situ non destructive study of 11 chair car systems and 34 man riding chair lift systems of SCCL.	GM(R&D) Singreni Collieries, Kothagudem Collieries, Dist - Khammam-507101 (T.S)

271.	07.06.2018	2018-19	2018-19	CNP/4680/2018-19	Evaluation and advice on the present condition of winder ropes of Turamdih Mines of Uranium Corporation of India Limited at Turamdih, Jharkhand".	The Chief Supdt.(Mech), Turamdih Mines, UCIL, P.O. –Sundarnagar, Dist - Singhbhum(East), Jharkhand-832107
272.	11.06.2018	2018-19	2018-19	CNP/4686/2018-19	Advice on the extraction sequence of Blocks 14 to 17 (along and across) and regional stability including scheme of strata control and monitoring in 14 seam at Jitpur Colliery of SAIL.	Dy.General Manager(Mines), Jitpur Colliery, SAIL, Collieries Division, P.O. – Jitpur Colliery, Dist-Dhanbad - 828309
273.	18.06.2018	2018-19	2017-18	SSP/255/2017-18	Slope stability condition of active mine slope at Malanjkhanda Copper Project, HCL for the year 2017-18	DGM (Mines)M/s HCL Malanjkhanda Copper Project Balaghat, M.P
274.	18.06.2018	2018-19	2017-18	CNP/4589/2017-18	Stability, planning and management of waste dumps of three pits of BIOM, Kirandul Complex	DGM (Mining) TS and E BIOM, Kirandul Complex, NMDC Ltd., Kirandul 494556, Distt. South Bastar, Dantewada(C.G.)
275.	18.06.2018	2018-19	2017-18	CNP/4551/2017-18	Advice on optimum slope design of pits and Dumps at 'B' block of Kumaraswamy Iron Ore Mines,NMDC	Jt General ManagerM/s NMDC Ltd., PO- Donimalai Taluk- Sandur, Dist-Bellary Karnataka-583118
276.	18.06.2018	2018-19	2018-19	SSP/287/2018-19	Assessment of Physico-mechanical properties of rock core samples of Total CBM Solution.	M/s Total CBM Solutions, India Pvt Ltd., 1952 Pijanji Kotla, Mubarakpur New Delhi- 110003
277.	18.06.2018	2018-19	2018-19	SSP/285/2018-19	Investigations to evaluate rock mechanical properties of rock cores from check holes of Subansiri Lower HE Project, NHPC, Gerukamukh.	M/s NHPC Subansiri Lower HE Project Kolaptukar, Dollungmukh CircleDist: Lower Subansiri Arunachal Pradesh
278.	21.06.2018	2018-19	2017-18	CNP/4677/2017-18	Advice on the status of stability of road alignment proposed by National Highways Authority of India in Jharia Coalfield, Dhanbad	GM (Tech) & Project Director, National Highways Authority of India, Office of the Project Director, Project Implementation Unit, NHAI-Complex – Kandra, PO- Bhitia,



						PS- Govindpur,Dhanbad-828109 (Jharkhand)
279.	02.07.2018	2018-19	2017-18	SSP/224/2017-18	Scientific study for Blast-induced ground vibrations at Aditya Limestone Mine of Aditya Cement Works,M/s. Ultratech Cement Ltd., Shambhupura, Chittorgarh, Rajasthan	Ultratech Cement Ltd., Adityapuram, Shambapura, Chitorgarh, Rajasthan - 312622
280.	03.07.2018	2018-19	2018-19	CNP/4691/2018-19	Assessment and advice on the present condition of haulage rope of mono-cable passenger ropeway at Science City, Kolkata.	M/s Damodar Ropeways & Infra Limited, 1/A, Vansittart Row, Kolkata – 700 001
281.	03.07.2018	2018-19	2018-19	CNP/4703/2018-19	Assessment and advice on the present condition of haulage rope at Nicco Parks & Resorts Limited at Salt Lake, Kolkata, West Bengal.	Manager(Engg.Dept.), Nicco Parks & Resorts Limited, Jheel Meel,Sec-IV, Salt Lake City, Kolkata – 700 106
282.	03.07.2018	2018-19	2018-19	CNP/4693/2018-19	Advice on assessment of water danger to Adriyala LW Project and design of water dams.	The General ManagerM/s SCCL Kothagudem Collieries-507101 Bhadrachalam Road Railway Station Bhadradi Kothagudem Dist. Telangana State.
283.	03.07.2018	2018-19	2014-15	CNP/4166/2014-15	Advice for safe depillaring and limit for strata control parameters in C-16 panel of No.1 seam at KTK Incline Mine, Bhupalpalli Area on the basis of the field data supplied by the mine	General Manager (R &D)M/s The SCCL Kothagudem Collieries-507101 Bhadrachalam Road Railway Station Khammam Dist.A.P.
284.	03.07.2018	2018-19	2018-19	SSP/294/2018-19	Scientific study on suitability of crushed overburden as a stowing material for underground mine	GM (Geology) M/s Hindalco Industries Limited Gare Palma IV/5 Mine Milupara, Tamnar, Raigarh (CG)

285.	13.07.2018	2018-19	2017-18	CNP/4644/2017-18	Advice on use of pond ash from Ramagudem Super Thermal Power Station, NTPC for underground stowing.	The AGM (EMG and AU)M/s NTPC P.O- Jyotinagar, Dist: Pedapalli, Telangana
286.	16.07.2018	2018-19	2018-19	CNP/4685/2018-19	Advice to design alternative method of depillaring in seam-II of Gare Palma IV/4 underground coal mines, Raigarh, with an aim to have no adverse mining induced subsidence effect on surface	Assistant Vice President-Mines, Hindalco Industries Limited, GarePalma Mines-IV/4,Vill. & PO – Milupara, Tehsil –Tamnar, Dist – Raigarh (Chattisgarh), PIN-496107
287.	16.07.2018	2018-19	2017-18	CNP/4534/2017-18	Analysis of Airborne Respirable Dust collected on Filter paper at Block-B Project (NCL	Project Officer, Block-B Project, P.O. – Gorbi, Dist –Singrauli (M.P.) –486 892
288.	16.07.2018	2018-19	2009-10	CNP/2282/2009-10	Study on soundness of the mechanical integrity of the vital components of all running winders of Lodna Area X, BCCL, Dhanbad, Jharkhand (India)	Area Manager (E&M), Lodna Area, BCCL, P.O.- Khas Jeenagora -828111, Dist - Dhanbad (Jharkhand)
289.	18.07.2018	2018-19	2017-18	CNP/4667/2017-18	Advice on evaluation of RMR and support design for decline and development roadways of different cross sections below 12MRL to - 395MRL at Mahagiri Mines (Chromite), IMFA Ltd	Shri Ashis Kumar Samantray, Mines Planning Cell, Indian Metals & Ferro Alloys Ltd.,IMFABuilding, Bomikhal, Rasulgarh, Bhubaneswar – 751010 (Odisha)
290.	23.07.2018	2018-19	2017-18	CNP/4584/2017-18	Assessment and Advice for the use of Electric Stacker for safe use in Zone 2 and Zone 22 hazardous area as per relevant ndian Standards	Godrej Material Handling M/s. Godrej & Boyce Mfg. Co. Ltd. Plant - 16, Design Dept. - Pirojshanagar, Vikhroli (E) Mumbai - 400079
291.	24.07.2018	2018-19	2018-19	SSP/288/2018-19	In situ non-destructive evaluation and advice on the present condition of two haulage ropes of aerial ropeway passenger cable car installations at Namchi, Gangtok, Sikkim	M/s Damodar Ropeways & InfraLimited, 1/A, Vansittart Row, Kolkata – 700 001

292.	24.07.2018	2018-19	2017-18	SSP/267/2017-18	In-situ non-destructive evaluation and advice on the present condition of track and haulage Ropes of bi-cable aerial ropeway passenger cable car installation at Gangtok, Sikkim	M/s Damodar Ropeways & Infra Limited, 1/A, Vansittart Row, Kolkata – 700 001
293.	24.07.2018	2018-19	2018-19	CNP/4699/2018-19	Assessment of insulation resistance (IR), high voltage (HV) and ingress protection test followed by 'NO LOAD' run test of motor rated at 225kW, 4 Pole, 3.3kV, 3 Phase, 50Hz., Frame size: DC280F710 for use in non-hazardous area of M/s Marathon Electric Motors (I) Ltd., Kolkata	M/s Marathon Electric Motors (India) Ltd., Large Machine Unit, 1, Taratala Road, Kolkata – 700 024
294.	24.07.2018	2018-19	2017-18	CNP/4548/2017-18	Feasibility extraction of IX/9-S panel with hydraulic sand stowing underbuilt-up area at Digwadih Colliery of Tata Steel Limited.	M/s Tata Steel Limited M/s Tata Steel Limited Digwadih Colliery Jamadoba Group Jharia Division Dist. Dhanbad Jharkhand
295.	25.07.2018	2018-19	2017-18	CNP/4663/2017-18	Study of blast-induced ground vibration, fragmentation, throw and flyrock during SME trial blasting in Patharia Limestone Mine and advice thereof	The Chief Manager Mining, Patharia Limestone Mine, ACC Limited, Jamul Cement Works, Dist-Durg-490024 (Chattisgarh)
296.	26.07.2018	2018-19	2018-19	SSP/295/2018-19 & CNP/4704/2018-19	Assessment of Physico-mechanical properties of rock core samples from Khottadih Colliery U/G borehole, Eastern Coal Field Ltd., and advice thereof.	Dy. General Manager (Mines/Agent) M/s ECL Khottadih Colliery Pandaveswar Area
297.	27.07.2018	2018-19	2017-18	CNP/4645/2017-18	Advice for improvement in rock fragmentation to enhance production and productivity with greater safety at Katamati Iron Mine of Tata Steel.	General Manager (OMQ) M/s Tata Steel Noamundi 833217 West Singhbhum, Jharkhand
298.	27.07.2018	2018-19	2017-18	CNP/4645/2017-18	Advice for improvement in rock fragmentation to enhance production and productivity with greater safety at Noamundi Iron Mine of Tata Steel.	General Manager (OMQ) M/s Tata Steel Noamundi 833217 West Singhbhum, Jharkhand

299.	27.07.2018	2018-19	2017-18	CNP/4645/2017-18	Advice for improvement in rock fragmentation to enhance production and productivity with greater safety at Joda East Iron Mine of Tata Steel.	General Manager (OMQ)M/s Tata Steel Noamundih 833217 West Singhbhum, Jharkhand
300.	27.07.2018	2018-19	2017-18	CNP/4645/2017-18	Advice for improvement in rock fragmentation to enhance production and productivity with greater safety at Khondbond Iron Mine of Tata Steel.	General Manager (OMQ)M/s Tata Steel Noamundih 833217 West Singhbhum, Jharkhand
301.	01.08.2018	2018-19	2016-17	SSP/156/2016-17	Adsoption Isotherm studies of carbonaceous shale/coal samples for characterization of shale horizons with respect to shale gas potentiality and quantitative estimation of shale gas resources by direct method in Mohuda sub-basin of jharia coalfield XII plan period .	The DDG M/s Natural Energy Resources, Mission II-B Geological Survey of India, DK-6, Sector-II, Salt Lake City, Kolkata-700091
302.	03.08.2018	2018-19	2018-19	CNP/4718/2018-19	Advice for optimization of blast design parameters at Bayal Quartz and Feldspar Mine to control ground vibration and air overpressure within safe limit for the safety of surrounding houses/structures with improved production and productivity.	GM (Mines) M/s Bayal quartz and feldpar mines Narnaul, Haryana -123023
303.	09.08.2018	2018-19	2017-18	CNP/4611/2017-18	Advice on evaluation of RMR at four locations in seams XI and XV of Jamadoba Colliery, Tata Steel Limited	The Head, Jamadoba Colliery, Tata Steel Limited, P.O.-Jamadoba, Jharia Division, Dist –Dhanbad -818 112
304.	14.08.2018	2018-19	2017-18	SSP/190/2017-18	Assessment and advice on strata monitoring during development of LCCM paneel in Seam No. II at Rani Atari Underground Mine, Chirimiri Area, SECL	Sub Area Manager, Office of the Sub Area Manager, Rani Atari Sub Area, Chirimiri Area, SECL, P.O. - West Chirimiri , Dist. - Korea (C.G.) PIN- 497773

305.	14.08.2018	2018-19	2017-18	CNP/4589/2017-18	Advice on Stability, planning and management of waste dumps of Deposit-10 & 11A of BIOM Bacheli Complex	DGM (Mining) TS and E BIOM, Kirandul Complex, NMDC Ltd., Kirandul 494556, Distt. South Bastar, Dantewada(C.G.)
306.	28.08.2018	2018-19	2018-19	CNP/4692/2018-19	Technical advice on electrical safety and healthiness of Electrical equipment installed at Bhagyam Oil & Gas mine in Barmer District in Rajasthan.	Coordinator-Regulatory Compliance M/s Vedanta Limited Cairn Oil & Ga RJON-90/1 Raj, Mangala Processing Terminal(MPT), Nagana Village, Via-Kawas N.H.No-112, HO Barmer, Rajasthan- 344001
307.	28.08.2018	2018-19	2017-18	CNP/4659/2017-18	Advice on electrical safety parameters of one no partially purged control panel Ex'P' in size of 1200(W) X 1500 (D) x 2140 (H) as per IS/IEC 60079:2-2007 and NFPA-496-2017 suitable for use in Gas Group IIC hazardous area.	M/s Electronics Instrumentation & Control Pvt., Ltd. M/s Electronics Instrumentation & Control Pvt., Ltd 56, Panchratna Industrial Estate Sarkhej- Bavlia Road, Taluka: Sanand Dist: Ahmedabad- 382213, Gujarat
308.	29.08.2018	2018-19	2015-16	CNP/4321/2015-16	Advice on optimum slope design of 420M deep Rampura Agucha mine, HZL	M/s HZL Rampura Agucha Mine Bhilwada, Rajasthan.
309.	29.08.2018	2018-19	2018-19	CNP/4712/2018-19	Advice on proposed final slope of dip side highwall and internal dump at North Searsole OC Patch (Phase-III), ECL.	The Agent M/s ECL North Searsole Colliery PO: Seasole Rajbari, Paschim Burdwan, Est Bengal- 713358.
310.	29.08.2018	2018-19	2018-19	CNP/4725/2018-19	Advice on proposed overall slope angle of Band I ore body and dump at Sukinda Mines (Chromite), IMFA	Senior Manager (Mines), IMFA, IMFA Building, Bhubaneswar - 751010 Odisha

311.	30.08.2018	2018-19	2018-19	CNP/4711/2018-19	Advice for ground stability over the underground galleries lying beneath and within 45m of railway acquired land and working in low cover area (Standing on pillars) at Durgapur Rayatwari Colliery (DRC), Chandrapur Area, WCL.	The Area General Manager M/s WCL Chandrapur Area, PO: Babupeth , Dist: Chandrapur, Maharastra- 442403
312.	30.08.2018	2018-19	2018-19	CNP/4721/2018-19	Advice on electrical safety parameters of one no. partially purged control panel Ex 'p' in size of 800mm (W)x1000mm(D)x2100mm(H) as per IS/IEC 60079:2-2007 and NEFA-496-2017 suitable for use in Gas Group IIC hazardous area	M/s Electronic Instrumentation & Control Pvt . Ltd., M/s Electronic Instrumentation & Control Pvt . Ltd 56, Panchratna Industrial Estate Sarkhej- Bavlia Road, Taluka: Sanand Dist, Ahmedabad- 382213 (Gujarat)
313.	30.08.2018	2018-19	2018-19	CNP/4719/2018-19	Advice for assessment of support requirement for development of RVII and RVIIA seam by LHCM at 3 & 4 Incline of Jhanjra Project Colliery, ECL.	Dy General Manager- Projects M/s Gainwell Commosales Private Limited Jhanjra House (Experts Hostel) ECL, PO- Jhanjra Dist- Paschim Burdwan, West Bengal
314.	10.09.2018	2018-19	2017-18	CNP/4672/17-18	Advice regarding safe movement of loaded railway rakes in proposed Merry-go-round alignment over the underground workings of Orient Mine No. 3 and 4: Stability analysis by numerical modelling	The DGM(Mines) OPGC, Odisha Odisha Power Generation Corporation (OPGC) Ib-Thermal Power Station, Banharpali, Jharsuguda - 768234
315.	12.09.2018	2018-19	2017-18	CNP/4604/2017-18	Analysis of airborne dust collected on filter paper at Khadia Project (NCL)	M/s. Northern Coalfields Ltd., Project Officer, Khadia Project, P.O. - Shaktinagar Dist. - Sonbhadra (U.P.) 231222
316.	20.09.2018	2018-19	2016-17	CNP/4454/2016-17	Studies and investigations of physico-mechanical & chemical properties for prototype steel Cog (50T) and Props (30T)	M/s Eastman Exports Pvt. Ltd., 49-A BRS Nagar, Ludhiana-141010

					upto 3 meter height.	
317.	09.10.2018	2018-19	2018-19	CNP/4736/2018-19	Evaluation and advice on the present condition of rope of cable car and ropes in flying eagle installed in Dreamland Amusement Park, Siliguri, West Bengal	Shri Ratan Kumar Bihani, M/s Lucky Exports India Pvt.Ltd.,327Bidhan Road, Near Auto Stand,Siliguri – 734001
318.	09.10.2018	2018-19	2018-19	SSP/302/2018-19	In situ evaluation and advice on the present condition of haulage rope of Pushkar site of M/s Damodar Ropeways & Infra Ltd.,Rajasthan.	M/s Damodar Ropeways & InfraLimited 1/A, Vansittart Row,Kolkata-700001
319.	09.10.2018	2018-19	2018-19	SSP/303/2018-19	In situ evaluation and advice on the present condition of haulage rope of detachable grip mono-cable passenger ropeway at Maihar, M.P	M/s Damodar Ropeways & InfraLimited 1/A, Vansittart Row,Kolkata-700001
320.	15.10.2018	2018-19	2018-19	CNP/4733/2018-19	Evaluation and advice on the present condition of haulage rope of Shri Naina Deviji monocable ropeway at Shri Naina Deviji, H.P.	M/s Damodar Ropeways & InfraLimited 1/A, Vansittart Row,Kolkata-700001
321.	29.10.2018	2018-19	2017-18	SSP/258/2017-18	Study and advice on blast induced ground vibration due to excavation of Additional Adit to HRT, Swara-Kuddu HEP, Hatkoti, HPPCL.	General Manager M/s Swara Kuddu HEP (111 MW) HPPCL,Hatkoti, Tehsil,Jubbal Dist: Shimla, HP-171206
322.	29.10.2018	2018-19	2017-18	SSP/199/2017-18	Strata monitoring of development workings in Salarjung seam at Shanthikhani Mine with Continuous Miner Technology, Mandamarri Area, SCCL	Chief General Manager (R and D), The Singareni Collieries CompanyLtd., Kothagudem Collieries - 507101, Bhadradri Kothagudem Dist., Telangana State

323.	29.10.2018	2018-19	2017-18	CNP/4553/2017-18	Advice on establishment of cut-out distance in CM panel of Salarjung seam at Shanthikhani Mine, Mandamari Area, SCCL	Chief General Manager (R and D), The Singareni Collieries Company Ltd., Kothagudem Collieries - 507101,  Bhadradri Kothagudem Dist., Telangana State
324.	17.03.2020	2019-20	2019-20	SSP/373/2019-20	Scientific Study for Slope Stability of Pit and Dump at Sukinda Mine (Chromite) of IMFA.	M/s Sukhinda Chromite Mines IMFA
325.	26.06.2019	2019-20	2019-20	SSP/374/2019-20	Slope Stability condition of active mine slope at Malanjkhanda copper project, HCL	HCL, Balaghat
326.	02.03.2020	2019-20	2019-20	SSP/N/376/2019-20	Scientific studies for design of safe blast parameters at M/s G. Jeevith Reddy Stone Quarry, Hyderabad, India.	Venkateshwara Traders
327.	02.03.2020	2019-20	2019-20	SSP/N/377/2019-20	Scientific studies for design of safe blast parameters at M/s Metarock Pvt. Ltd., Thiruvananthapuram, Kerala.	Metarock Pvt. Ltd., Thattamala
328.	12.07.2019	2019-20	2019-20	SSP/378/2019-20	In-Situ Non-Destructive Evaluation and advice on the present condition of haulage rope at solang nallah, Manali, H.P	Ski Himalayas Ropeway Pvt. Ltd.
329.	19.02.2020	2019-20	2019-20	SSP/386/2019-20.	Assessment and advise for mechanical integrity of 8T C.S. Gear components at Bhagabandh Colliery, BCCL.	Bhagabandh Colliery, BCCL
330.	20.03.2020	2019-20	2019-20	SSP/389/2019-20	Study on blast optimization at Sukinda Chromite Mine vis-a vis monitoring of blast induced vibration and qualitative assessment of explosive and its accessories.	Tata Steel Limited



331.	24.09.2019	2019-20	2019-20	SSP/409/2019-20	Assessment and Technical Advice on Surface Temperature Rise Classification of Flameproof Motor Rated 700KW, 6.6KV/2P, Frame Size: 1MJ7710-2, For use in Zone 1 & 2 for Gas group IIC atmosphere	M/s Bharat Heavy Electricals Limited
332.	24.09.2019	2019-20	2019-20	SSP/410/2019-20	Assessment and Technical Advice on Surface Temperature Rise Classification of Flameproof Motor Rated 850KW, 6.6KV/2P, Frame Size: 1MJ7714-2, For use in Zone 1 & 2 for Gas group IIC atmosphere.	M/s. Bharat Heavy Electricals Limited
333.	25.09.2019	2019-20	2019-20	SSP/411/2019-20	In Situ Evaluation and advice on the present condition of haulage rope of detachable grip mono-cable passenger ropeway at Maihar, M.P.	Damodar Ropeway & Infra Limited
334.	14.11.2019	2019-20	2019-20	SSP/412/2019-20	In Situ Non-Destructive evaluation and advice on the present condition of track and haulage ropes of bi-cable aerial ropeway passenger cable car installation at Gangtok, Sikkim.	Damodar Ropeway & Infra Limited
335.	15.10.19	2019-20	2019-20	SSP/413/2019-20	In-Situ Evaluation and advice on the present condition of track and haulage ropes of passenger ropeway across river brahmaputra at guwahati for m/s Guwahati Metropolitan Development Authority, Assam.	M/s Samir Damodar Ropeways Pvt. Ltd
336.	05.02.2020	2019-20	2019-20	SSP/426/2019-20	In-Situ Non-Destructive study and advice on the present condition of track and haulage ropes of bi-cable joshimath-auli ropeway, haulage rope of chair lift, haulage ropes of two ski lift of garhwal mandal vikas nigam limited (GMVN), Joshimath.	Garwal Mandal Vikash Nigam Limited (GMVN)
337.	22.01.2020	2019-20	2019-20	SSP/429/2019-20	Assessment and Advice on T-Class and overpressure of Flameproof Motor Rated 700KW, 6.6KV/2P, Frame Size: E630L, For use in hazardous area.	M/s CG Power and Industries Solution Limited

338.	16.01.2020	2019-20	2019-20	SSP/431/2019-20	In-Situ Investigation and advice on the present condition of four nos.of track ropes and two nos. of haulage ropes of passenger cable car aerial ropeway installation of m/s timber trail, asia resorts limited, Parwanoo (H.P.)	M/s Timber Trail
339.	18.02.2020	2019-20	2019-20	SSP/433/2019-20	In-Situ Nondestructive evaluation and advice on the present condition of winding ropes of mahagiri mines (chromite) of Imfa ltd., Odisha.	IMFA Ltd.,Kaliyapani –Odisha
340.	15.01.2020	2019-20	2019-20	SSP/437/2019-20	Assessment of Physico mechanical Properties of four borehole from Pachwara South Coal block of Rajmahal Coalfield, Dumka, Jharkhand	M/s Inspectorate Griffith India Pvt.Ltd
341.	19.03.2020	2019-20	2019-20	SSP/440/2019-20	In-Situ Nondestructive Evaluation and advice on the present condition of winding ropes of Chasnalla Colliery, Jharkhand.	Chasnalla Colliery, SAIL
342.	27.04.2020	2020-21	2019-20	SSP/441/2019-20	Investigation on Methane Emission for Categorization of Degree of Gassiness of Coal Seam R-VI of Pure Searsole Colliery, Satgram Area, ECL and Advice on Associated Hazards.	Eastern Coalfields Limited
343.	17.03.2020	2019-20	2019-20	SSP/446/2019-20	Assessment and Technical Advice on Surface Temperature Rise Classification and Overpressure of Flameproof Motor Rated 1HP/4P, Frame Size: 80FLP IF3, Rated 2HP/4P, Frame Size: 90S/L FLP IE3 and Rated 20HP/4P, Frame Size: 160M/L FLP IE3 For use in Hazardous Area of M/s. HEM Industries, Mumbai.	M/s Hem Industries
344.	14.10.2020	2020-21	2020-21	SSP/476/2020-21	Investigation on Methane Emission for Categorization of Degree of Gassiness of Brindaban and Kalimati Coal seams of Badjna Colliery, Mugma Area, ECL and Advice on Associated Hazards.	Eastern Coalfield Limited.

345.	17.06.2020	2020-21	2020-21	SSP/478/2020-21	Assessment of different rock formations for their phyco mechanical aspects of BH#APBS-64 (P-57) of Bhalukassba Surni Phase-III block, Rajmahal Coalfield.	M/s CMPDIL
346.	17.06.2020	2020-21	2020-21	SSP/479/2020-21	Assessment of different rock formations for their physico-mechanical aspects of BH#MLP-180, Labji-Pusla (Sector-II) block of Sonhat Coalfield, Chattishgarh.	M/s CMPDIL
347.	17.06.2020	2020-21	2020-21	SSP/480/2020-21	Assessment of different rock formations for their physico-mechanical aspects of BH# MJT-36, Block-Jharpalam Thangarghat, Mand-Raigarh Coal field, Raigarh.	M/s CMPDIL
348.	17.06.2020	2020-21	2020-21	SSP/488/2020-21	Assessment of Physico-mechanical properties of BH # 18, 41 and 59 from Talabira mines of Talabira Mining Pvt. Ltd., Odisha.	M/s Talabira (Odisha) Mining Pvt. Ltd., Adani
349.	19.11.2020	2020-21	2020-21	SSP/N/493/2020-21	Numerical Modelling Studies for Subsidence Prediction at Rampura Agucha Mine, HZL.	Rampura Agucha Mine, Hindustan Zinc Ltd.,
350.	12.03.2021	2020-21	2020-21	SSP/N/494/2020-21	Scientific study on vibration monitoring and design of safe charge pattern at Parackal granite Stone Quarry, Ernakulam.	M/s Parackal Granite Kerela Pvt. Ltd.,
351.	16.09.2020	2020-21	2020-21	SSP/497/2020-21	Assessment of Physico-mechanical properties of Khudia and Birmati Reservoir Schemes in Jharkhand, Central Water Commision, Itanagar, Arunachal Pradesh.	M/s Central Water Commission,
352.	19.11.2020	2020-21	2020-21	SSP/N/500/2020-21	Three dimentional numerical modelling for designing stable stop dimensions for Kherataria Wellastonite & amp Calcite Mine of M/s Wolkem Industries Ltd.,	Wolkem Industries Limited
353.	31.08.2020	2020-21	2020-21	SSP/505/2020-21	Study to estimat Geo-technical properties of BH#CDNC-36 for mine design and coal exploration of Deonad III Block, N.K. Coalfield	M/s CMPDIL

354.	07.09.2020	2020-21	2020-21	SSP/509/2020-21	study to estimate Geo-technical properties of rock coresamples of BH#PMPT-01 & 02, Mining Associate Pvt.Ltd.,Asansol	M/s Mining Associate Pvt. Ltd.,
355.	26.03.2021	2020-21	2020-21	SSP/511/2020-21	Instrumentation scheme and monitoring of backfilling stope blocks of Mahagiri Mines, IMFA.	A.M.(Mines) Indian Metals & Ferro Alloys Ltd.,
356.	05.01.2021	2020-21	2020-21	SSP/524/2020-21	In situ evaluation and advice on the present condition of track and haulage ropes of passenger ropeway across river Brahmaputra at Guwahati for m/s Guahati Metropolitan Development Authority, Assam.	M/s Samir Damodar Ropeways Pvt. Ltd., Forest Campus, Panbazar Near D.C. Court Guwahati-781001, Assam
357.	13.03.2021	2020-21	2020-21	SSP/547/2020-21	Scientific investigation on methane emission and determination of in situ gas content for categorization of degree of gassiness of R-VIIC seam of Nakrakonda-Kumardih 'B' colliery, Bankola area, Eastern Coalfields Limited and advice on hazards. azards.	M/s Eastern Coalfield Limited Bankola Area, PO- Ukhra Dist-Burdwan, 713363 West Bengal
358.	17.03.2020	2019-20	2019-20	CNP/4809/2019-20.	Advice on slope stability condition of X-Quarry at Sukinda Chromite Mine, Odisha, Tata Steel.	Sukinda Chromite Mine
359.	19.05.2020	2020-21	2019-20	CNP/4811/2019-20	Advice on fly ash filling in Gare Pelma sector III opencast coal mine using ash from CSPGCL.	CSPGCL ,Raipur
360.	07.02.2020	2019-20	2019-20	CNP/4821/2019-20.	Advice for improvement in rock fragmentation to enhance production and productivity with greater safety at Noamundi, Katamati, Joda East and Khondbond Iron Mines of Tata Steel.	Tata Steel
361.	03.07.2019	2019-20	2019-20	CNP/4823/2019-20	Advice for designing of controlled blasting patterns at Mukutban limestone & dolomite mining project of m/s RCCPL Pvt. Ltd.	M/s RCCPL Pvt. Limited

362.	14.02.2020	2019-20	2019-20	CNP/4842/2019-20	Advice on sand and coarse aggregate/murum samples regarding mining project of Banda (UP).	Environmental Research and Analysis
363.	02.03.2020	2019-20	2019-20	CNP/4843/2019-20	Advice on Review of Mining Plan of Jyoti Pahari Kyanite Mine	JSMDCLimited
364.	20.03.2020	2019-20	2019-20	CNP/4848/2019-20	Advice for improvement in rock fragmentation to enhance production and productivity with greater safety at Sukinda Chromite mine of Tata Steel Ltd.	Procurement Sukinda Chromite Mine
365.	29.07.2019	2019-20	2019-20	CNP/4862/2019-20	Advice on use of ash from DCP with overburden at Gare Pelma IV/1 Opencast mine, Tamnar Phase- III(4)	The Head (Environment) DCP, JSPL,CG
366.	25.11.2019	2019-20	2019-20	CNP/4866/2019-20	Advice for strata monitoring instrumentation and preparation of instrumentation plan for K2 panel of R-V seam at Khottadih Colliery, ECL	Eastern Coalfields Limited
367.	14.02.2020	2019-20	2019-20	CNP/4869/2019-20	Advice for optimization of blast design parameters at Bailadila Opencast Mine, Bacheli Complex, NMDC to improve productivity of the mine with effective utilization of explosive energy and reduction of blasting hazards.	M/s NMDC Ltd.
368.	20.03.2020	2019-20	2019-20	CNP/4871/2019-20	Advice on fill optimization for Rajpura Dariba Mine, HZL.	M/s Hindustan Zinc Limited
369.	04.02.2020	2019-20	2019-20	CNP/4872/2019-20	Design for Induced caving by Blasting for the Depillaring Workings of the King Seam at PVK 5 Incline Mine, SCCL for the Designated CM Project Area of M/s GainwellComosales Private Limited	Gainwell Commosales Private Limited
370.	25.11.2019	2019-20	2019-20	CNP/4878/2019-20	Advice on electrical safety parameters of one no. partially Purged Control Panel Ex 'p' Z- Type in size of 1000mm(L) x 800(W) x 2100(H) & 600mm(L) x 600mm(W) x 2100mm(H) as per IS/IEC 60079:2-2007	M/s Electronic Instrumentation & Control Pvt. Ltd.

					and NFPA-496-2008 suitable for use in hazardous area	
371.	25.11.2019	2019-20	2019-20	CNP/4883/2019-20	Advice for designing of controlled blasting parameters for safety of nearby houses/structures at stone quarry located at Mauza Katnikol, Block No. 15, Sheikhpura, Bihar.	M/s Broadway Links Pvt.Ltd.
372.	27.04.2020	2020-21	2019-20	CNP/4886/2019-20	Advice on suitability of crushed OB for cemented backfill at Mahagiri mine, IMFA	Head Mining Business Unit,IMFA
373.	17.03.2020	2019-20	2019-20	CNP/4887/2019-20	Advice on Suitability of Bottom Ash for stowing at Jitpur colliery, SAIL.	Jitpur Colliery,SAIL
374.	25.11.2019	2019-20	2019-20	CNP/4894/2019-20	Advice for Preparation of Strata Control and Monitoring Plan (SCAMP) for the Development of XI Seam of Jamadoba Colliery, Tata Steel Limited	Tata Steel Limited
375.	22.01.2020	2019-20	2019-20	CNP/4901/2019-20	Optimum design of external dumps of 120m height and internal dump upto ultimate pit limited at PakriBarwadih Coal Mining Project of NTPC Ltd.	Manager,Geology
376.	15.01.2020	2019-20	2019-20	CNP/4905/2019-20	Advice on pit slope Stability of Kerandari 'A' Coal Block.	Sikri Site Office, Kerandari CMP
377.	25.11.2019	2019-20	2019-20	CNP/4908/2019-20	Advice for Preparation of Strata Control and Monitoring Plan (SCAMP) for the Development of VIII Seam of 6&7 Pits Bhutgoria Amalgamated Colliery, Tata Steel Limited.	M/s Tata Steel Limited
378.	20.03.2020	2019-20	2019-20	CNP/4909/2019-20	Advice on use of coal ash from DCPP with overburden at Gare Palma IV/1 opencast mine, Tamnar – Phase IV(1)	DCPP, Jindal steel & power limited(CG)

379.	15.01.2020	2019-20	2019-20	CNP/4912/2019-20	Advice for Preparation of Strata Control and Monitoring Plan (SCAMP) for the Depillaring of XV/4-S Panel in XV Seam of Jamadoba Colliery, Tata Steel Limited	Tata Steel Limited (TSL)
380.	09.03.2020	2019-20	2019-20	CNP/4919/2019-20	Advice on preparation of Strata control and monitoring plan for 'V'seam (23/8 incline) of Bhowra (N) UG Mine, E.J. Area, BCCL.	Bhowra (N) UG Mine
381.	27.05.2020	2020-21	2019-20	CNP/4921/2019-20	Advice on instrumentation scheme and monitoring on backfilling of stope blocks 1,4P and 6P at Mahagiri mine, IMFR.	IMFA, Bhubaneswar
382.	15.01.2020	2019-20	2019-20	CNP/4923/2019-20	Advice on use of coal ash from DCPD with oberburden at Gare Palma IV/1 opencast mine, Tamnar- Phase IV(2)	DCPD, Jindal steel & power limited (CG)
383.	29.01.2020	2019-20	2019-20	CNP/4928/2019-20	Advice on study for depillaring of 124LW panel by Continuous Miner (CM) Technology in East Block of Churcha Mine (RO), Baikunthpur Area, SECL.	M/s GMMCO Limited
384.	15.01.2020	2019-20	2019-20	CNP/4929/2019-20	Advice for controlled blasting at stone mine No. 4 of Arena Food & Agro Industries Pvt. Ltd., Sheikhpura, Bihar to keep ground vibrations, noise/air overpressure and flyrocks within safe limits.	M/s Arena Food & Agro Industries Pvt. Limited
385.	17.03.2020	2019-20	2019-20	CNP/4932/2019-20	Advice for optimization of blast design parameters at Rawan Limestone Mine to improve productivity with due safety to the structures in the periphery of the mine.	M/s Ambuja Cement Limited
386.	04.02.2020	2019-20	2019-20	CNP/4933/2019-20	Advice on Slope Steepening and Optimum Pit Slope Design for Quarry D of South Kaliapani Chromite Mine of OMC Ltd.	The Odisha Mining Corporation Ltd.
387.	17.03.2020	2019-20	2019-20	CNP/4937/2019-20	Advice on stability of underground workings and overlying strata at Talcher coalfields, MCL.	MCL

388.	17.03.2020	2019-20	2019-20	CNP/4940/2019-20	Advice on electrical safety parameters of Three Nos. Partially Purged Control Panel Ex 'p' in size of 1600mmx800mmx2000mm, 1000mmx800mmx1600mm and 800mmx800mmx1600mm as per IS/IEC 60079:2-2007 and NFPA-496-2017 suitable for use in hazardous area of M/s. Electronic Instrumentation & Control Pvt. Ltd., Ahmedabad (Gujarat)	M/s Electronic Instrumentation & Control Pvt. Ltd
389.	07.02.2020	2019-20	2019-20	CNP/4942/2019-20	Scientific study and advice for controlled blasting practices to minimize ground vibration, fly-rock, Air overpressure at Gere Stone Mine of M/s Katyayni Contractors Pvt. Ltd.	M/s Katyayni Contractors Pvt. Ltd.
390.	19.05.2020	2020-21	2020-21	CNP/4952/2020-21	Advice for depillaring of 16 East Panel by Continuous Miner (CM) Technology in East Block of Churha Mine (RO), Baikunthpur Area, SECL	M/s GMMCO Limited
391.	19.05.2020	2020-21	2020-21	CNP/4953/2020-21	Advice on use of coal ash from DCPD with overburden at Gare Pelma IV/1 opencast mine, Tamnar-Phase IV(3)	The Head (Environment) DCPD, JSPL
392.	04.05.2020	2020-21	2020-21	CNP/4955/2020-21	Advice for designing of controlled blasting patterns for the safety of nearby residential structures at Talabira - II & III OCP .	M/s Talabira (Odisha) Mining Pvt. Limited
393.	25.06.2020	2020-21	2020-21	CNP/4958/2020-21	Advice on use of coal ash from Jharsuguda Captive Power Plant for filling in underground mines.	Vedanta Limited The Head (Environment) Jharsuguda Captive Power Plant, Vedanta Limited, Jharsuguda, Odisha-768201
394.	11.05.2020	2020-21	2020-21	CNP/4959/2020-21	Scientific study for Slope Stability of Slime Dump of Katamati Iron Ore Mine and advice thereon for Tata Steel Limited.	Tata Steel Limited Manager-Procurement, Tata Steel Limited, OMQ Division PO-Noamundi, Dist-West Singhbhum, Jharkhand-833217



395.	16.09.2020	2020-21	2020-21	CNP/4960/2020-21	Scientific Study for Slope Stability of Gare Palma IV/4 and advice thereon for Hindalco Industries Ltd.	Hindalco Industries Limited Gare Palma IV/4 Coal Mine, PO-Milupara, Raigarh-496107
396.	18.09.2020	2020-21	2020-21	CNP/4961/2020-21	Scientific Study for Slope Stability Analysis of Pit and Dump and advice thereon for Chatti-Bariatu Coal Mining Block, NTPC	NTPC Ltd. SSC-Coal Mining(Ranchi) Kerandari CMP Sikri Site Office, PO-arkagaon,Hazaribagh Jharkhand-825311
397.	19.05.2020	2020-21	2020-21	CNP/4962/2020-21	Blast vibration prediction and suggestion of blast designs for initial mining operations at Sonadih Limestone Mines(ML-1) considering the safety of nearby surface features.	M/s Nuvoco Vistas Corp. Ltd. Sonadih Cement Plant P.O. Raseda, Dist-Baloda bazarChhatisgarh-493332
398.	21.02.2021	2020-21	2020-21	CNP/4965/2020-21	Advice for Preparation , Formulation and Implementation of Strata control and monitoring plan as per CMR-2017 (123) for Depillaring of Panel No. 45 of No.3 seam NCPH Colliery R-6 Mine, Chirimiri Area, SECL.	Sub Area Manager, NCPH SubArea, South Eastern Coalfields Area P/oO- Haldibari, Dist: Korea (Chattisgarh)PIN- 495006
399.	17.06.2020	2020-21	2020-21	CNP/4966/2020-21	Advice on electrical safety parameter of pressurized (Ex'p') Motor Rated at 10580KW, 6.6KV, 4Pole in Frame Size 1TH4943-4as per IS/IEC:60079-2:2014 for use in Zone-1 and gas Group IIA, IIB &IIC hazardous area.	M/s Bharath Heavy Electrical Limited Industrial Machine Sales,division,Annexe, Block- II Piplani, Bhopal
400.	17.06.2020	2020-21	2020-21	CNP/4967/2020-21	Advice on Electrical Safety parameters of three nos. of increased safety Ex 'eb' and Non-Sparking Ex 'ec' motors rated at 1200KW, 11KV, 4Pole, Frame Size: 1SJ7632-4; 2750KW, 11KV, 2Pole, Frame Size: 1SJ1713in hazardous areas.	M/s. Bharat Heavy Electrical Limited,AME Division,Block-II, EW, II Floor, BHEL Bhopal - 462022
401.	04.06.2020	2020-21	2020-21	CNP/4970/2020-21	Optimal design and stability analysis of overburden dump at South Kaliapani Chromite Mine and advice thereon for Odisha Mining Corporation Ltd.,	DGM (Mining) , Project Cum Monitoring Cell Odisha Mining Corporation Ltd.,OMC House, Bhubaneswar- 751001,India

402.	04.06.2020	2020-21	2020-21	CNP/4971/2020-21	Advice on use of coal ash from DCPD with overburden at Gare Pelma IV/1 opencast mine, Tamnar - Phase IV (4).	DCPD, JSPL, CG
403.	19.03.2021	2020-21	2020-21	CNP/4975/2020-21	Advice for design of extraction methodology for development and depillaring of RV seam using continuous miner at MIC, Jhanjra Project Colliery,ECL	M/s Gainwell Mining private Limited Godrej waterside, Tower II, Unit 705, Block DP, Sector V, Salt Lake, Kolkata-700091, West Bengal
404.	06.08.2020	2020-21	2020-21	CNP/4978/2020-21	Advice for depillaring of 15 East Panel by Continuous Miner Technology in East Block of Churcha Mine (RO), Baikunthpur Area, SECL.	M/s GMMCO Limited Kumar Sadan, (SECL), 90 unit, Opp: Mahajan Stadium, PO: Churcha Colliery, Dist.: Korea, Chattisgarh - 497339
405.	07.01.2021	2020-21	2020-21	CNP/4981/2020-21	Advice on use of coal ash from DCPD with overburden at Gare Palma IV/1 opencast mine, Tamnar	The Head (Environment)Jindal Steel & Power Raigarh-496001 C.G
406.	20.08.2020	2020-21	2020-21	CNP/4982/2020-21	Scientific Study of Slope Stability for OB Dumps and Pit Slope and advice therein for Bharatpur OCP, Bharatpur Area, McL	Staff Officer (Safety & Training) Mahanadi Coalfields Limited, Talcher, Bharatpur Area ,PO-N.S. NagarDist- Angul-759148
407.	15.09.2020	2020-21	2020-21	CNP/4986/2020-21	Advice for depillaring of the 7D Panel by Continuous Miner technology at Churcha East Block of Churcha Mine (RO), Baikunthpur Area, SECL.	M/s GMMCO Limited, SECL 90 unit, Opp: Mahajan Stadium PO: Churcha Colliery, Dist:Korea,Chattisgarh-497339
408.	24.08.2020	2020-21	2020-21	CNP/4987/2020-21	Advice on technical evaluation of safe and sustainable underground operation at gare Palma IV/5 Coal mine of m/s Hindalco Industries Limited, Raigarh(CG)	M/s Hindalco Industries LimitedGare Palma IV/5 Coal mine Vill- 7 PO: Milupara Tehsil: R PIN:Raigarh, 496107 Chattisgarh

409.	16.09.2020	2020-21	2020-21	CNP/4989/2020-21	Advice on pit slope and high wall slope stability of QAB and QSE quarries of West Bokaro Collieries of Tata Steel.	Tata Steel Ltd., West Bokaro Ghatotand, Dist- Ramgarh Jharkhand-815314
410.	14.12.2020	2020-21	2020-21	CNP/4990/2020-21	Scientific study for ultimate pit slope design and advice thereon for Gare Palma IV/4 coal mine	M/s Hindalco Industries Ltd., Gare Palma-IV/4 Bankheta-496107 Raigarh (CG)
411.	28.10.2020	2020-21	2020-21	CNP/4992/2020-21	Advice on electrical safety parameter of Pressurized (Ex'p') Motor Rated at 1430KW,6.6KV,4 Pole in Frame Size 1SB7636-4 for use in Zone- 1 & 2 for Gas Group IIC Hazardous areas.	M/s Bharat Heavy Electrical Limited Block-II, EW,II Floor BHEL, Bhopal-462022
412.	28.10.2020	2020-21	2020-21	CNP/4993/2020-21	Scientific study for slope stability, ultimate pit slope design and dump slope design and advice thereon for ROCP/S Jhanjra Mine of Bastacolla Area IX, BCCL.	M/s BCCL,Bastacolla Area IX Dhanbad, Jharkhand
413.	02.12.2020	2020-21	2020-21	CNP/4997/2020-21	Advice for evaluation of RMR at Patmohana Colliery, Sodepur Area, ECL.	Chief Mining Manager eastern Coal Field Limited Patmohana Colliery, Sodepur Area, Distt. - Burdwan -713371W.B.
414.	26.03.2021	2020-21	2020-21	CNP/4999/2020-21	Scientific study and advice as per regulation 196 (2) , (3) and (4) of the CMR 2017 for controlled deep hole blasting at Ara-Kundi-Devalgadda and Chsmatu Patches of Magadh OcP, Magadh-Amrapali Area.	Office of the General Manager Central Coalfields Limited Magadh -Amrapali Area Akashdeep Main Road, Dakra PO- Dakra, PIN- 829210 Dist-Ranchi, Jharkhand
415.	18.01.2021	2020-21	2020-21	CNP/5001/2020-21	Scientific study for RMR determination of combined seam (geo. V/VI/VII seam) at Mahespur Colliery, Govindpur Area, BCCL.	Project Officer, Mahespur colliery Bharat Coking Coal Limited Govindpur Area-III, BCCL, Dist: Dhanbad- 828128 Jharkhand
416.	26.02.2021	2020-21	2020-21	CNP/5003/2020-21	Advice on Barricade design and high density hydraulic fill at Mocha and Paste fill at Zawarmala mines.	Head (Backfilling) Hindusthan Zinc Limited Zawar Mines, HZL, Udaipur

417.	23.11.2020	2020-21	2020-21	CNP/5004/2020-21	Scientific study and advice on designing of controlled blasting pattern for safety of surface of features at Argat Limestone Mine of Sidhi cement Works.	Mine Manager Ultratech Cement Limited(Unit-Sidhi Cement works) Jaypee Vihar, Majhigawan, Sidhi(MP)
418.	18.12.2020	2020-21	2020-21	CNP/5005/2020-21	Advice for designing of controlled blasting patterns for carrying out safe blasting operations near the electric lines at Khandbandh Iron Ore Mines of M/s Sree Metaliks Limited, Odisha.	Khandbandh Iron Ore Mine M/s Sree Metaliks Limited Barbil-758035, Odisha.
419.	26.03.2021	2020-21	2020-21	CNP/5006/2020-21	Advice on stability of the construction site for DAV School at Lingaraj area, MCL.	General Manager Mahanadi Coalfields Limited Lingaraj Area, Angul
420.	19.02.2021	2020-21	2020-21	CNP/5008/2020-21	Advice on electrical safety parameters of Oil Mist Console/Generator for suitable use in hazardous area Zone 2, Gas Group IIA/IIB/IIC.	FEPL ENGG Private Limited 424, Raheja Arcade, Sector-II, CBD Belapur, Thane, Maharashtra,400614
421.	19.03.2021	2020-21	2020-21	CNP/5011/2020-21	Scientific study and advice thereon for the Design of Pit slope Slope of AADOCM, Dhori Area, CCL.	Central Coalfields Limited AADOCM, Dhori Area, Dist-Bokaro
422.	21.02.2021	2020-21	2020-21	CNP/5014/2020-21	Advice for the depillaring of 114L West Panel by continuous Miner Technology in the East Block of Churha Mine (RO) , Baikunthpur Area, SECL.	M/s GMMCO Limited Kumar Sadan (SECL), 90 Unit Opp: Mahajan Stadium PO: Churha Colliery, Dist:Korea, Chattisgarh-497339
423.	19.03.2021	2020-21	2020-21	CNP/5015/2020-21	Advice on subsidence prediction and management study pertaining to Jaganathpur-B coal block of raniganj coalfield	Power Plus Traders Pvt. Ltd., 39, Shakespeare Sarani , Premlata Building, 6th floor, Kolkata-700017
424.	04.02.2021	2020-21	2020-21	CNP/5019/2020-21	Advice for depillaring of the 97L East panel by continuous Miner Technology in the East Block of Churha Mine (RO) Baikunthpur Area, SECL.	M/s GMMCO Limited Kumar Sadan (SECL), 90 Unit, Opp:Mahajan Stadium, PO-Churha Colliery, Dist: Korea,Chattisgarh-497339

425.	13.03.2021	2020-21	2020-21	CNP/5022/2020-21	Advice on design of FRS barricade for hydraulic filled stopes of Rajpura Dariba Mines.	Hindusthan Zinc Limited Yasad Bhawan Udaipur-313004
426.	19.03.2021	2020-21	2020-21	CNP/5023/2020-21	Advice on use of bottom ash as a stowing material for underground mines of Chasnalla.	Steel Authority of India Limited Chasnalla Colliery, Dist- Dhanbad, Jharkhand
427.	26.03.2021	2020-21	2020-21	CNP/5028/2020-21	Scientific study for assessment of blasting impact on the surrounding environment and advice for designing of controlled blasting patterns at Dalpahar Iron and Manganese Mines of M/s D.C.Jain, Keonjhar, Odisha.	Dalpahar Iron and Manganese Mines of D.C. Jain (MDO-Triveni Earthmovers Pvt. Limited) Dist.- Keonjhar, Odisha.
428.	19.03.2021	2020-21	2020-21	CNP/5030/2020-21	Scientific study for pit slope stability and advice thereon for religara colliery, central Coalfields Limited	Religara Colliery, CCL Argada Area, dist-Hazaribagh-829129
429.	26.03.2021	2020-21	2020-21	CNP/5031/2020-21	Scientific study and advice on designing of controlled blasting pattern for safety of surface features at Budgauna and Majhgawan Limestone Mines of M/s Ultratech Cement Ltd., (Unit : Sidhi Cement Works)	Ultratech Cement Limited Unit -Sidhi Cement Works Jaypee Vihar, Majhgawan, Sidhi (MP) 486776
430.	26.03.2021	2020-21	2020-21	CNP/5035/2020-21	Advice on use of coalash from DCP with overburden at Gare Pelma IV/1 opencast mine, Tamnar (V/1).	The Head (Environment) Jindal Steel & Power Limited Post Box No, 16, Kharsia Road Raigarh-496001, (C.G) India, Raigarh
431.	26.03.2021	2020-21	2020-21	SSP/511/2020-21	Instrumentation scheme and monitoring of backfilling stope blocks of Mahagiri Mines, IMFA.	A.M.(Mines) Indian Metals & Ferro Alloys Ltd., IMFA Building, Bhubaneswar- 751010 Odisha
432.	05.04.2021	2021-22	2020-21	TSP//0065/2020-21	Study to estimate Geo-technical properties of BH#MBC-27, Barangada Copper Block, Rakha-Chapri Project, MECL, Giridih Jharkhand.	Project Manager MECL Pani Manganese Project, Kadwal Chowkri, Pavi-Jetpur Dist--Chota Udepur Gujarat-391160

433.	05.04.2021	2021-22	2019-20	CNP/N/4906/2019-20	Geotechnical study for the advice on pit slope and waste dump stability at the Grasim Cement Limestone mine.	Ultratech Cement limited Vill-mohanpura, teh Kotputli Dist- Jaipur (Rajasthan) 303108
434.	05.04.2021	2021-22	2019-20	CNP/4938/2019-20	Design of blind backfill system for the unapproachable areas at Talcher coalfields, MCL- an advice thereof.	The General Manager MCL Talcher Area, At/PO. Dera Dist- Angul, Odisha-759103
435.	20.04.2021	2021-22	2020-21	CNP/5043/2020-21	Slope stability study for Design of Pit and Dump slopes and advice thereon for Band-I Quarry at Sukinda Mine (Chromite), IMFA Ltd.,	Indian Metals & Ferro Alloys Limited Sukinda, Dist- Jaipur, Odisha, PIN-755047
436.	11.06.2021	2021-22	2018-19	SSP/306/2018-19	Study and advice for blasting optimization at Balaria, Baroi, Mochia and Zawarmala underground mines of M/s Hindustan Zinc Limited for safe and efficient exploration of minerals.	M/s Hindustan Zinc limited (Zawargroup of Mines) Commercial- Zawar Mines Udaipur, Rajasthan-313901
437.	15.06.2021	2021-22	2020-21	CNP/5009/2020-21	Advice on heating and formation of explosive mixture in R-V seam of Kunustoria Colliery and establishing reentry protocol of the same.	Eastern Coalfield Limited Kunustoria Area Post- Toposi, Dist- Burdwan, W.BPIN-713362
438.	15.06.2021	2021-22	2020-21	CNP/5042/2020-21	Study and advice for mining operation practices & optimization of blast design parameters at Baghai Mine to control vibration & air-overpressure within safe limit for the safety of habitation , road, Railway line and determination of safety distance or the same.	M/s Prism Johnson Limited(Cement Division) Vill- Mankhari, PO- Bathia Tehsil: Rampur Bhagelan Dist: Santa (M.P) PIN-493332
439.	15.06.2021	2021-22	2020-21	CNP/5044/2020-21	Advice on scientific study to negotiate distributed/fall zone in the Bottom Gate of proposed D-16 Panel at XVI TOP Seam of Moonidih Project, BCCL.	Bharat Coking Coal Ltd.,(BCCL) Moonidih Colliery, PO- Moonidih Dist-Moonidih, Dhanbad-828129
440.	15.06.2021	2021-22	2020-21	CNP/5033/2020-21	Geotechnical study and advice thereon for design of pit and dump slopes of FACOR Mines (Vedanta limited), Odisha.	Ferro Alloys Corporation Limited Charge Chrome Plant, D P Nagar, PO- - Randia Dist- Bhadark , Odisha, India PIN-756135

441.	20.04.2021	2021-22	2019-20	CNP/4834/2019-20	Advice for determining the Incubation Period, Fire risk potentials of coal stack, OB dump and coal benches of Dulanga Coal Mining project of NTPC Ltd, Sundargarh (Odisha).	DGM 9Mining)NTPC Limited Dulunga Coal Mining Project 2nd Floor , Megh Mallahar , Mission Road Sundargarh-770001 (Odisha).
442.	24.04.2021	2021-22	2018-19	CNP/4772/2018-19	Advising the methodology to deal with fire at integrated coal mining Limited, Sarisatolli Coal Mine, CESC Ltd (WB).	Agent Sarisatolli Coal Mine, CESC Ltd. CESC House, Chowringhee SquareKolkata- 700001 (WB)
443.	23.06.2021	2021-22	2020-21	CNP/5020/2020-21	Scientific study for re-designing and advice on controlled blasting parameters at Western Quarry of Pakri Barwadih Coal Mining Project, NTPC Limited, Hazaribag , Jharkhand	Thriveni Sainik Mining Pvt LimitedC/o NTPC Ltd., Langatu, PO- Barkagaon Hazaribag-825311, Jharkhand
444.	24.04.2021	2021-22	2017-18	SSP/195/2017-18	Slope monitoring studies at Donimalai Iron Ore Mine (DIOM) and Kumaraswamy Iron Ore Mine (KIOM) of NMDC Ltd.,	Jt General Manager (Prodn) M/s NMDC Ltd., Donimalai Complex PO- Donimalai Taluk-Sandur, Dist: Bellary Karnataka-583118
445.	20.04.2021	2021-22	2019-20	CNP/4897/2019-20	Advice for slope stability of pit and External Dump for Ena Colliery, Kusunda Area, BCCL.	Project Officer BCCL, Ena Colliery Kusunda Area-VI, BCCL.
446.	20.04.2021	2021-22	2020-21	CNP/5010/2020-21	Advice for safe method of pillar extraction in the Panel Nos. 1 & 2 of Lower orkable Seam using continuous miner technology at Tawa-II underground coal mine, Pathakhera Area, WCL.	Trident & Auro Mining LLP Titanium, Plot No 1-98/8/75A &75B, Jubilee Enclave, Madhapur,Hyderabad, Telangana-500081

447.	11.06.2021	2021-22	2019-20	CNP/4930/2019-20	Advice on stability of railway track and railway acquired land of MJC line of S.E. Railway in Hurladih colliery of Bharat Coking Coal Limited	Project Officer, BCCL Bharat Coking Coal Limited Huriadih Colliery, P.B.Area, PO- Bhaga 828301, Dhanbad
448.	11.06.2021	2021-22	2020-21	CNP/5017/2020-21	Advice on the feasibility of development and depillaring of RVI and rVI seams using continuous Miner (CM) at Kumardihi "B" Mine ECL for the CM project of Gainwell Commosales Private Limited.	Gainwell Commosales Private Limited Jhanjra House (Experts Hostel) Eastern Coalfields Limited PO- Jhanjra-713385 dist- Paschim Burdwan, West Bengal
449.	03.06.2021	2021-22	2021-22	CNP/5057/2021-22	Scientific study and advice on Pit slope stability and other associated work at Religara Colliery, Argada Area, CCL.	Project Officer Central Coalfields Limited Office of the Project Officer, Religara Dist- hazaribagh Jharkhand-829129
450.	31.05.2021	2021-22	2020-21	CNP/5029/2020-21	Scientific study and advice thereon for the Design of Pit and Dump Slope of Bandedpur Colliery, Sijua Area, BCCL.	Project Officer BCCL, Bansdeopur Colliery, Sijua Area, 828121 (JH)
451.	13.05.2021	2021-22	2020-21	CNP/4996/2020-21	Advice for design of extraction methodology for development and depillaring of Sector-F of RVII and RVIIA seams using Low Height Continuous Miner at 3&4 Incline, Jhanjra Project Colliery, ECL.	Shri Shantanu Sarkar General Manager-UG Projects, Gainwell Commosales Private Limited, Jhanjra House (Experts Hostel), Eastern Coalfields Limited, P.O - Jhanjhra - 713385, Dist. Paschim Burdwan, WB.
452.	13.05.2021	2021-22	2018-19	SSP/N/312/2018-19	Development of a mining method to extract directly below pastefill & GCMP Audit at Sindeshar Khurd Mine, HZL.	M/s Hindustan Zinc Ltd., Sindeshar Khurd Mine, Yashad Bhawan, Udaipur, Rajasthan



453.	16/17.06.2021	2021-22	2020-21	CNP/4979/2020-21	Advice on stability of workings below railway tracks of SER at Patnsaongi Mine of nagpur Area, WCL	WCL Nagpur Area General Manger, Nagpur Area WCL PO-Jaripatka, Dist-Nagpur 440014
454.	06.06.2021	2021-22	2020-21	CNP/4989/2020-21	Advice on pit slope and high wall slope stability of QAB and QSE quarries of West Bokaro Collieries of Tata Steel.	Tata Steel Ltd., West Bokaro Ghatotand, Dist- Ramgarh Jharkhand-815314
455.	18.05.2021	2021-22	2020-21	TSP/0073/2020-21	Assessment of safety parameter of Flameproof Air condition for use in HAZardous atmosphere.	M/s Shreya Ex-Tech Pvt. Ltd., Block No.700, manjusar Savli Road Manjusar, Tunday, Vadodara-391775
456.	13.05.2021	2021-22	2018-19	SSP/N/317/2018-19	Ground control management plan audit at Mochia and Balaria Mine for 2 years 2018-2020, HZL.	Zawar Group of Mines Hindustan Zinc limited Yasad Bhawan, Udaipur, Rajasthan
457.	13.05.2021	2021-22	2018-19	CNP/N/4727/2018-19	Consultation contract for stope design using numerical modelling for 2 years (2018-2020) at Sindeshar Khurd Mine, HZL.	M/s Hindustan Zinc Ltd., M/s Hindustan Zinc Ltd., Sindeshar Khurd Mines,
458.	13.05.2021	2021-22	2018-19	CNP/N/4742/2018-19	Consultation contract for stope design using numerical modelling for 2 years (2018-2020) at Mochia and Balaria Mine, HZL.	M/s Zawar Group of Mines M/s Zawar Group of Mines Hindustan Zinc Limited
459.	23.06.2021	2021-22	2020-21	TSP/0077/2020-21	Study to estimate Geo-technical properties of BH# 03 & 04 Incline of Jhanjra Project Colliery, ECL.	M/s Gainwell Commosales Pvt. Ltd., 3 and 4 Incline, Jhanjra Project Colliery, PO- Balijuri (Jhanjhara) Jhanjhara W W.B-713385
460.	23.06.2021	2021-22	2020-21	SSP/554/2020-21	Study to estimate Geo-technical properties of Borehole for mine design and coal exploration of kumardihi-B Colliery, ECL	M/s Gainwell Commosales Pvt. Ltd., Nakrakonda-Kumardihi-B Colliery bankola Area, Ukhra, Kumardihi Paschim Buwan-713333

						West Bengal
461.	29.06.2021	2021-22	2021-22	CNP/5053/2021-22	Scientific study and advice for assessment of ground vibration generated from blasting operations at Block No.01 Stone Quarry, Manpur, Gaya, Bihar.	Project Manager Block No. 01 Stone Quarry Vill- Mirzapur, Manpur Dist- Gaya, Bihar
462.	05.07.2021	2021-22	2020-21	CNP/5045/2020-21	Advice for the depillaring of 108L West panel by Continuous Miner technology in the Eaqtst Block of Churcha Mine (RO), Baikunthpur Area, SECL	M/s GMMCO Limited Churcha Colliery beside Colliery Manager's office Churcha, West Mine(SECL), PO-Churcha Colliery, Churcha, Chattisgarh, India- 497337
463.	14.07.2021	2021-22	2021-22	CNP/5062/2021-22	Advice on use of coal ash from DCPD with overburden at gare Pelma IV/1 opencast mine, Tamnar (V/1)	M/s Jindal Steel & Power Limited M/s Jindal Steel & Power Limited Post Box No 16, Kharsia Road Raigarh 496001 (C.G) India Raigarh
464.	14.07.2021	2021-22	2020-21	TSP/0072/2020-21	Study to estimate Geo-technical properties of BH# 01 & 02 of Jhanjra Project Colliery, ECL.	M/s Gainwell Commosales Pvt.Ltd., Main Industrial Complex Jhanjhara Project , Colliery, Jhanjhara (W.B) 713385
465.	14.07.2021	2021-22	2020-21	TSP/0068/2020-21	Study to estimate Geo-technical properties of BH#MAPL/STD/001 and MINOP-002, Muraidih U/G Mines, Minop Inovative Technologies Pvt. Ltd.,	M/s Minop Inovative Technologies Pvt. Ltd., Dhansar, Dhanbad-828106